

**Accord Auto Services Pte Ltd** (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003070547-01	Date of Loss:	24/06/2023
Vehicle Reg. No.:	<b>SLF8760M</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YIU ZHEN YE		
Driver:	YIU ZHEN YE		

Make/Model:	CHEVROLET SONIC, 1.4 HB 2WD (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	SILVER		
Engine No:	A14XER151800040	Chassis No:	KL1TA69FJGB512980
Odometer:	0 KM		

Paint Type:  
Total Loss?  
Est. Duration of Repair (day)

**NO**

5

Present Location: **ACCORD AUTO SERVICES PTE LTD (HQ)****COST OF CLAIMS**

	<b>Amount</b>
Parts	6,494.40
Miscellaneous Items	2,240.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>8,884.40</b>
<b>+ GST 8.00% (S\$)</b>	<b>710.75</b>
<b>Nett Amount (S\$)</b>	<b>9,595.15</b>

This claim is handled by: **GOH JACQUELINE**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 01 Jul 2023)  
**Parts:** 144      **CHEVROLET SONIC 1.4 HB 2WD (A) (Catalogue:Merimen Singapore 1.0)**  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** **Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28**  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

~~90264255~~  
97400999

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	*1,500.00 F BUC
2	1		*FRONT BONNET HINGE RH	0.00	0.00	*40.00 F } XNN
3	1		*FRONT BONNET HINGE LH	0.00	0.00	*40.00 F } XNN
4	1		*FRONT BONNET LOCK	? 0.00	0.00	*107.00 F } XNN
5	1		*FRONT BONNET SEAL	0.00	0.00	*17.00 F } XNN
6	1		*FRONT BONNET STOPPER	0.00	0.00	*3.00 F } XNN
7	1		*FRONT BONNET INSULATOR	0.00	0.00	*110.00 FXNN
8	1		*FRONT HEADLAMP LH	0.00	0.00	*850.00 FCRA
9	1		*FRONT HEADLAMP RH	0.00	0.00	*850.00 FXNN
10	1		*FRONT GRILLE ASSY	0.00	0.00	CUT *290.00 F } XNN
11	1		*FRONT EMBLEM	0.00	0.00	*100.00 F } XNN
12	1		*FRONT BUMPER	0.00	0.00	*930.00 F OD
13	1		*FRONT BUMPER SIDE RETINER RH	0.00	0.00	*10.00 FXNN
14	1		*FRONT BUMPER SIDE RETINER LH	0.00	0.00	*10.00 F } XNN
15	1		*TOWING COVER	0.00	0.00	*17.00 FXNN
16	1		*FRONT LH FOGLAMP	0.00	0.00	*290.00 FXNN
17	1		*FRONT LH FOGLAMP GARNISH	0.00	0.00	*37.00 FXNN
18	1		*FRONT RH FOGLAMP	0.00	0.00	*290.00 FXNN
19	1		*FRONT RH FOGLAMP GARNISH	0.00	0.00	*37.00 FXNN
20	1		*FRONT REINFORCEMENT BAR	0.00	0.00	*320.00 F } XNN
21	1		*SUPPORT PANEL	0.00	0.00	*56.00 FXR

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>5,904.00</b>
<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>590.40</b>
<b>Total Parts (S\$)</b>	<b>6,494.40</b>

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	1,000.00 <sup>500</sup>
2	1	SPRAY PAINT ON ALL AFFECTED AREA	1,000.00 <sup>500</sup>
3	1	TO APPLY ANTI RUST TREATMENT	120.00 <sup>50</sup>
4	1	TO CHECK WIRING SYSTEM	120.00 <sup>30</sup>
<b>Sub Total (S\$)</b>			<b>2,240.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	FRONT NUMBER PLATE WITH FRAME	New	45.00 <sup>CRA</sup>
2	FRONT BUMPER CLIPS	New	35.00 <sup>NEC</sup>
3	FRONT LH & RH FENDER INNER SHIELD CLIPS	New	70.00 <sup>XNN</sup>
<b>Gross Labour Cost (S\$)</b>			<b>150.00</b>

Accord Auto Services Pte Ltd/SLF8760M/01/07/2023 10:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not Authorise  
 - Excess = TBA  
 - L/S or P/P repair?  
 - Resurvey before paint if P/P repair.  
 - Desk Top survey by Simon (6 256 3561)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: