

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2006079714-01	Date of Loss:	30/06/2023
Vehicle Reg. No.:	SNJ5178U	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM TOMMY	Contact No:	+6596339800
Driver:	LIM WEI YUNG		
Make/Model:	BYD E6 (ME-2), (A)	Vehicle Reg. Date:	06/07/2022
Vehicle Colour:	BLUE		
Engine No:	0	Chassis No:	LC0CE4DC7N0090379
Odometer:	14666 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	14,146.00
Miscellaneous Items	585.00
Labour	2,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	17,701.00
+ GST 8.00% (\$\$)	1,416.08
Nett Amount (\$\$)	19,117.08

This claim is handled by: HENRY LEE YOON SANGGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jul 2023)**Parts:** M1-MPV BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ding Auto Pte Ltd/SNJ5178U/03/07/2023 16:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*950.00 F
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*40.00 F
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*40.00 F
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*1,000.00 F
5	1		*FRONT BUMPER SIDE COVER RH	0.00	0.00	*65.00 F
6	1		*FRONT BUMPER SIDE COVER LH	0.00	0.00	*65.00 F
7	1		*FRONT BUMPER TOW CAP	0.00	0.00	*25.00 F
8	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*85.00 F
9	1		*BONNET	0.00	0.00	*1,250.00 F
10	1		*BONNET HINGE RH	0.00	0.00	*50.00 F
11	1		*BONNET HINGE LH	0.00	0.00	*50.00 F
12	1		*BONNET INSULATOR	0.00	0.00	*110.00 F
13	1		*BONNET LOCK	0.00	0.00	*115.00 F
14	1		*FRONT GRILLE CHROME MOULDING WITH BADGE	0.00	0.00	*580.00 F
15	1		*FRONT FENDER RH	0.00	0.00	*875.00 F
16	1		*FRONT FENDER LH	0.00	0.00	*875.00 F
17	1		*FRONT FENDER INNER COVER RH	0.00	0.00	*155.00 F
18	1		*FRONT FENDER INNER COVER LH	0.00	0.00	*155.00 F
19	1		*FRONT SUPPORT PANEL CPL	0.00	0.00	*550.00 F
20	1		*FRONT PANEL UPPER GARNISH	0.00	0.00	*200.00 F
21	1		*FRONT SIDE UPPER PANEL RH	0.00	0.00	*45.00 F
22	1		*FRONT SIDE UPPER PANEL LH	0.00	0.00	*45.00 F
23	1		*RADIATOR WITH FAN COWLING COMPLETE UNIT	0.00	0.00	*2,150.00 F
24	1		*RADIATOR AIR GUARD RH	0.00	0.00	*65.00 F
25	1		*RADIATOR AIR GUARD LH	0.00	0.00	*65.00 F
26	1		*CONDENSOR ASSY	0.00	0.00	*975.00 F
27	1		*FRONT SENSOR MODULE	0.00	0.00	*580.00 F
28	1		*HEADLAMP ASSY RH	0.00	0.00	*850.00 F
29	1		*HEADLAMP ASSY LH	0.00	0.00	*850.00 F

F=Franchise part.

Sub Total (\$\$)	12,860.00
+ Margin on L,N Items 10.00% (\$\$)	1,286.00
Total Parts (\$\$)	14,146.00

Ding Auto Pte Ltd/SNJ5178U/03/07/2023 16:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	ECU/MODULE - DIAGNOSTIC & RE-SETTING	350.00
2	1	FRT BUMPER, GRILLE, INNER COVER & GARNISH/PANEL - CLIPS	200.00
3	1	FRT NUMBER PLATE & FRAME	35.00
Sub Total (S\$)			585.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,000.00
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,000.00
3	EV BATTERY - DISCONNECT & RE-CONNECT POWER SUPPLY	New	250.00
4	REMOVE & INSTALL - ECU/MODULE COMPONENTS	New	250.00
5	REMOVE & INSTALL - RADIATOR & CONDENSOR COMPONENTS	New	150.00
6	REFILL - RADIATOR COOLANT	New	80.00
7	REFILL - AIR COND GAS	New	80.00
8	ALIGN HEADLAMP & TEST WIRING	New	80.00
9	ALIGN MODULE SENSOR & TEST WIRING	New	80.00
Gross Labour Cost (S\$)			2,970.00

Ding Auto Pte Ltd/SNJ5178U/03/07/2023 16:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >