

REPAIRING OF  
MOTOR VEHICLES,  
PANEL BEATING,  
WELDING, SPRAYING,  
INSURANCE AGENT,  
CLAIMS  
DEALING IN 2ND  
HAND VEHICLE.

# 速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT  
1 Kaki Bukit Ave 6 Blk D 01-91, Singapore 417883  
Tel: 6747 7858, 6747 2343 Fax: ~~6742 0012~~ 65090072  
E-mail: slmoi@singnet.com.sg  
Reg No. 206639/00K

修 理 汽 車 貨 車 兼  
打 嗎 甲 燒 烝 噴 漆  
代 理 保 險 : 車 禍  
賠 償 及 買 賣 汽 車

MS WONG HSIAO HWEI @CECILIA WONG

DATE: 04/07/2023

DOA : 29/06/2023

## ESTIMATE REPAIR FOR VEHICLE NO. SMT 2821A (HONDA ODYSSEY)

	<u>Description</u>	<u>List Price</u>
1 pc	Rear tailgate	\$ 1,380.00
2 pcs	Tailgate hinge @\$78.00	\$ 156.00
1 pc	Tailgate lock (assy)	\$ 283.65
1 pc	Lower catch	\$ 65.00
1 pc	Weatherstrip	\$ 155.50
1 pc	Tailgate logo	\$ 68.00
1 pc	Tailgate Odyssey emblem	\$ 70.00
2 pcs	Tailgate reverse lamp @\$480.50	\$ 961.00
1 pc	Tailgate outer lock handle	\$ 185.00
1 pc	Tailgate chrome outer garnish	\$ 330.00
1 pc	Tailgate U chrome lower	\$ 235.00
1 pc	Tailgate innerboard	\$ 298.00
2 pcs	Tailgate side garnish @\$85.00	\$ 170.00
1 pc	Wiper arm	\$ 91.50
1 pc	Wiper blade	\$ 85.00
1 pc	Wiper motor	\$ 338.00
1 pc	Rear windscreen glass	\$ 1,380.00
1 set	Repair kit	\$ 248.00
2 pcs	Tailgate damper @\$250.00	\$ 500.00
1 pc	Rear bumper	\$ 720.50
2 pcs	Bumper side retainer @\$48.50	\$ 97.00
4 pcs	Bumper reverse sensor @\$320.00	\$ 1,280.00
2 pcs	Bumper bracket @\$99.50	\$ 199.00
2 pcs	Bumper reflector @\$95.00	\$ 190.00
2 pcs	Bumper lower spoiler L & R @\$185.60	\$ 371.20
10 pcs	Bumper clips @\$6.50	\$ 65.00
2 pcs	Taillamp @\$1160.20	\$ 2,320.40
2 pcs	Taillamp panel @\$200.90	\$ 401.80
2 pcs	Taillamp lower garnish @\$155.80	\$ 311.60

1 pc	Rear end panel	\$	590.20
1 pc	End panel garnish	\$	190.90
1 pc	Rear floor panel	\$	1,380.50
1 pc	Rear floor panel carpet (assy)	\$	470.00
1 pc	Rear rh fender	\$	1,270.90
1 pc	Rh fender innerboard	\$	885.90
1 pc	Rh fender cover railing top panel	\$	250.00
2 pcs	Fender glass end chrome moulding @S\$188.00	\$	376.00
1 pc	Rear silencer box	\$	790.80
2 pcs	Rear mounting @S\$55.00	\$	110.00
		\$	19,271.35
	Less : 20%	\$	(3,854.27)
		\$	15,417.08

Special Nett Items

Towing fee	\$	80.00
To remove & fix rear windscreen glass	\$	150.00
Rear windscreen gum	\$	50.00
To remove & fix rear fender glass	\$	100.00
Fender glass gum	\$	50.00
To remove & fix L & R fender garnish, rear set	\$	200.00
To spray anti-rust	\$	150.00
Remove & fix rear cooling coil & refill gas	\$	200.00
To remove & fix rear silencer box	\$	100.00
Floor panel insulation pad	\$	250.00
Remove & fix wire and check wiring	\$	90.00
Labour charges for knocking & replacing parts.	\$	3,000.00
Spraypainting	\$	2,800.00
TOTAL :	\$	<u>22,637.08</u>