



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23006705/Uqy3m4 Date: 27/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 1868B	Veh. Inspected	FBT 3915L	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/23/2069	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	03/07/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CB200X	c.c	184	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	ME4MC563LMA002618	Colour	SILVER	
Odometer	11596 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110-70-17	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140-70-17	MICHELIN	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/06/2023	Inspection Date	04/07/2023	
Survey held at	BAN HOCK HIN CO.PTE LTD BLK 8 DEFU SOUTH STREET 1, #04-28 JTC DEFU INDUSTRIAL CITY, SINGAPORE 533758			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	