

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6

#02-03 AutoBay

SINGAPORE 417883

TEL.NO: 93365311 / FAX NO. 67411019

Email: eurosucccess0202@gmail.com

not Arthur

4/7/23

2/5 \$ 4000/

4 days

Estimate Report

To : Claim Department
 Attn :
 Tel :
 Fax :

Vehicles Number : GBH 1860L
 Make and Model : TOYOTA HIACE
 Date Of Accident : 23.06.2023

Attn: Motor Claim Department
 Estimated Repairs Costs

Qty	List Items	Unit Price	Amount
1	Rear tail gate	Body 20/3000	\$ 2,067.00
2	Rear tail gate stopper	11 \$ 25.00	\$ 50.00 X
2	Rear tail gate damper	11 \$ 225.00	\$ 450.00 X
1	Rear tail gate weatherstrip	11 \$	405.00 X
2	Rear tail gate corner garnish	\$ 30.00 11	\$ 60.00 X
1	Rear tail gate outer moulding	11 \$	328.00 X
1	Rear tail gate lock motor	11 \$	542.00 X
1	Rear tail gate inner lock	Dange 11 \$	285.60
1	Rear tail gate lower lock	11 \$	49.50 X
1	Rear tail gate inner trim board	11 \$	295.60 X
1	Rear tail gate wiper motor	11 \$	523.00 X
1	Rear tail gate wiper arm	11 \$	172.00 X
1	Rear tail gate windscreen moulding	MS \$	362.00 X
2	Rear tail lamp	MS \$ 412.00	\$ 824.00 12C 386
2	Rear tail lamp lower garnish	\$ 249.30 R	\$ 498.60 X
1	Rear bumper	DL \$	486.30
2	Rear bumper L-R retainer	\$ 60.00 11	\$ 120.00 12C
1	Rear bumper step panel reinforcement	300 \$	284.30
1	Rear end panel - outer	20/3000 \$	597.20
1	Rear end panel - inner	R \$	871.20 X
Total		\$	9,271.30
Less 25%		\$	2,317.83
		\$	6,953.48

Special nett item

Rear tail gate trimboard clip	11	\$	50.00 X
Rear bumper clip	11	\$	50.00 30
Rear number plate with holder	11	\$	60.00 X
Rear tail gate logo	11	\$	93.00 520
Rear tail gate "HIACE" sticker	11	\$	40.00 30 X
Rear tail gate "70" sticker	11	\$	30.00 10
Rear tail gate "8" sticker '8 per'	11	\$	30.00 10
Rear bumper sensor	one	\$	450.00 200
Rear windscreen sealant	11	\$	90.00 40

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6

#02-03 AutoBay

SINGAPORE 417883

TEL.NO: 93365311 / FAX NO. 67411019

Email: eurosuccess0202@gmail.com

Estimate Report

To : Claim Department
Attn :
Tel :
Fax :

Vehicles Number : GBH 1860L
Make and Model : TOYOTA HIACE
Date Of Accident : 23.06.2023

Attn: Motor Claim Department
Estimated Repairs Costs

Qty	List Items	Unit Price	Amount
		Total	\$ 7,846.48

Labour & Misc Charges

To transfer Rear tailgate mechanism	\$	300.00	60
To check electrical wiring	\$	120.00	20
To apply undercoating on accident parts	\$	250.00	60
To remove and refix rear windscreen glass	\$	200.00	120
To respray painting and ETC	\$	1,300.00	600
Panel beating, cut, weld rear panel tailgate and replacing above parts	\$	1,600.00	800
Total	\$	3,770.00	1660
Grand Total	\$	11,616.48	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 4166-4
252
3124.80
340
1660
5124.8
202
4099