

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741

Fax : 6746 7939

Not Authorised

4/7/23

03-Jul-23

Vehicle Reg No. : GBM 1243 S

Model : SUZUKI EVERY

2/5 \$5000

5 days

telephone After 1pm

Estimated repair cost for the vehicle as mentioned above

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Rear windscreen inner foam tape <i>all</i>	\$ 65.00 ✓
1	Rear windscreen inner seal <i>all</i>	\$ 95.00 ✓
1	Rear tailgate <i>body</i>	\$ 1,895.00 ✓
2	Rear tailgate dampers <i>all</i>	\$ 237.00 X
1	Rear tailgate inner lock <i>Door / L/R</i>	\$ 211.55 ✓
1	Rear tailgate inner lock remote <i>11</i>	\$ 165.20 X
1	Rear tailgate inner trim board <i>Trim</i>	\$ 189.50 ✓
1	Rear tailgate outer handle <i>11</i>	\$ 42.50 X
1	Rear tailgate rubber <i>Trim</i>	\$ 162.80 ✓
1	Rear tailgate "S" emblem <i>all</i>	\$ 48.50 ✓
1	Rear tailgate "EVERY" sticker <i>all</i>	\$ 28.00 ✓
1	Rear bumper lamp RH <i>300</i>	\$ 525.00 ✓
1	Rear end panel <i>DD</i>	\$ 665.00 ✓
1	Rear end panel inner member <i>1</i>	\$ 596.00 X
1	Rear end panel inner air vent <i>11</i>	\$ 65.00 X
1	Rear bumper <i>DD / To. 1</i>	\$ 1,480.00 ✓
1	Rear bumper lamp LH <i>one</i>	\$ 489.50 ✓
2	Rear bumper side retainers <i>300 / all</i>	\$ 85.00 ✓
1	Rear spare tyre carrier <i>1</i>	\$ 325.00 X
1	Rear spare tyre carrier lock catch <i>11</i>	\$ 78.00 X
1	Rear spare tyre mat <i>11</i>	\$ 488.50 X
1	Rear spare tyre panel <i>1</i>	\$ 1,650.00 X
1	Rear exhaust silencer <i>11</i>	\$ 780.00 X
1	Rear exhaust mounting <i>11</i>	\$ 38.00 X
1	Rear fender -RH <i>11</i>	\$ 1,150.00 X
		\$ 11,555.05
	Less 5% <i>152</i>	\$ 577.75
		\$ 10,977.30

Special Nett Items

1	Rear windscreen sealant	1pc	\$	80.00	40
1	Rear tailgate "70KM/H" sticker	1pc	\$	28.00	10
1	Rear tailgate "4PAX" sticker	1pc	\$	28.00	10
1	Rear tailgate company sticker	1pc	\$	250.00	150
1	Rear bumper clip (1 set)	1pc	\$	50.00	✓
1	Rear number plate with holder	1pc	\$	50.00	40
1	Rear reverse sensor (1 set)	malfunction	\$	350.00	200
1	Rear reverse camera	1pc	\$	480.00	X
				\$	1,316.00

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	11 150.00	X
3	To remove and refit rear reverse sensor and camera.	\$	120.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$	80.00	60
5	To apply undercoating.	\$	90.00	60
6	Panel beating.	\$	1,400.00	800
7	To re-spray painting on the affected areas.	\$	1,300.00	800
		\$	3,220.00	

Grand Total :

\$ 15,513.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4699.8
152
3994.83
500
1190
6284.83
202
5027