



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF23006719/y3

ACCIDENT CLAIMS SECTION

Date: 04/07/2023

(SPORE POLICE FORCE)

POLICE LOGISTICS BASE (PLB)

1 HEMMANT ROAD SINGAPORE 438675

Code: SPF

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 5227C	Veh. Inspected	GBL 6393P
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/045 (LK)	Excess (\$)	0.00
Assign From	LAI PENG CHONG	Assign Date	03/07/2023

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	26/06/2023	Inspection Date
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969	

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--