



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC23006724/Kvy3e2

Date: 14/07/2023

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GT 1023P	<b>Veh. Inspected</b>	SJL 3630E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	23/23/23/VC05/027643	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	04/07/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA CAMRY (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	MR053BK4107038865	<b>Colour</b>	METALLIC BLACK
<b>Odometer</b>	210930 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	YOKOHAMA	8 mm
<b>L/H Front Tyre</b>	215/60 R16	YOKOHAMA	8 mm
<b>R/H Rear Tyre</b>	215/60 R16	YOKOHAMA	8 mm
<b>L/H Rear Tyre</b>	215/60 R16	YOKOHAMA	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/07/2023	<b>Inspection Date</b>	05/07/2023
<b>Survey held at</b>	AUTHORIZE WORKSHOP PTE LTD 160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**