

(08/11/13) wof

ASS. REC. BY: pm

REF: CS4

A4123006725/R2Y3

0306

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLR 516SMat Workshop m/s MAXIMUS AUTOof 7 Down Lest St #05-05

Insured:

AGI

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

131K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 61K

Veh No:

SLR 516SM

Yr Regn:

2017 / AUGType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W S30I MSPT

c.c

1998

Colour

BLUG

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJAS2070W 607459Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/07/23

D.O.I.

05/07/23

Survey held at

MAXIMUS AUTODes. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

MAXIMUS AUTO SERVICES PTE LTD

Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

quiry Hotline : +65 9797 3113 / Fax : +65 6250 1081

-mail : Sales@MaximusRacing.com



ESTIMATION FOR SLR5165M

Reference No: Q-23-151

Date: 1/7/2023

Terms: **Cash**

Requested By:

Address:

Tel:

Item	Description	Qty	Unit Price	Disc %	Total Price
Policy No // Accident Date: Towed In: 03/07/2023 Vehicle Make/Model: BMW 530i G30 Saloon Vehicle Number: SLR 5165 M Manufacturing Year: 2017 Engine: 191016Z0495PT306 Chassis No: WBAJA52070WC07459					
Parts & Material Part Location					
a. drawing - 51_2883 - Support, front					
1	Carrier, bumper front <i>bt</i>	1	1		
2	Impact absorber - top <i>cm</i>	2	1		
3	Carrier, bumper, front bottom <i>bt</i>	3	1		
4	Impact absorber - front bottom <i>cm</i>	4	1		
5	Kerb shock absorber	10	2		
6	Adapter left	11	1		
7	Adapter right	11	1		
8	Vertical connection left	12	1		
9	Vertical connection right	12	1		
10	Covering cross member <i>cm</i>	13	1		
b. drawing - 51_4125 - M trim panel, front					
11	Panel, bumper front <i>de</i>	1	1		
12	Flap for towing eye front <i>X</i>	2	1		
13	Guide, top left <i>cm</i>	4	1		
14	Guide, top right <i>cm</i>	4	1		
15	Guide, bumper, left	5	1		
16	Guide, bumper, right	5	1		
17	Trim, trim grille, front	7	1		
18	Support, fog lamp left <i>cm</i>	8	1		
19	Support, fog lamp right <i>cm</i>	8	1		
20	Set, mounting, PDC/PMA sensor, front <i>X</i>	9	1		
21	License plate holder	10	1		
c. drawing - 51_4126 - M trim panel, trim elements, front <i>34</i>					
22	Grille, air inlet, middle <i>cm</i>	1	1		
23	Grille, air inlet, open left <i>X</i>	4	1		
24	Grille, air inlet, open right <i>X</i>	4	1		
25	Left finisher <i>X</i>	5	1		
26	Right finisher <i>X</i>	5	1		
27	Cover, grille, left <i>X</i>	6	1		
28	Cover, grille, right <i>X</i>	6	1		
d. drawing - 51_3128 - Air ducts					
29	Air duct, radiator, top <i>cm</i>	1	1		
30	Air duct, radiator, bottom <i>cm</i>	2	1		
31	Air duct, bottom <i>cm</i>	3	1		
32	Air flaps, top <i>cm</i>	4	1		
33	Air-flap control, active, top	5	1		
34	Air duct, brake, wheel arch, left	6	1		
35	Air duct, brake, wheel arch, right	6	1		
36	Air duct, brake left	7	1		
37	Air duct, brake right	7	1		
38	Air duct, side panel, inner left	11	1		
39	Air duct, side panel, inner right	11	1		
e. drawing - 51_Z630 - exterior trim / grille					
40	Grille, front left <i>cm</i>	1	1		
41	Grille, front right <i>cm</i>	1	1		
f. drawing - 13_1825 - Air duct					
42	Intake grille	1	1		
43	Intake duct	2	1		
44	Rubber element	3	1		
g. drawing - 71_0998 - Radiator mounting parts					
	Radiator Heat exchanger	1	1		
	Radiator	2	1		
	Fastening elements	3	2		
	Cooling module mounting, top	4	2		
	Cover top	5	1		

Covering right ?	6	1
Covering left ?	6	1
Holder, module mounting, bottom left ?	7	1
Holder, module mounting, bottom right ?	7	1
Module mounting, left ?	8	1
Module mounting, right ?	8	1
Covering lower <i>cm</i> /	9	1
Rock guard ?	13	1
h. drawing - 17_0987 - Fan housing, mounting parts		
Fan housing with fan ?	1	1
Fan cowl with acoustic ring ?	2	1
i. drawing - 17_1033 - Cooling system coolant hoses		
Hose radiator - water pump ?	1	1
Pipe radiator - expansion tank ?	2	1
Line, expansion tank ?	5	1
Pipe, electric coolant pump ?	7	1
Hose radiator ?	9	1
Pipe, radiator-cylinder head ?	10	1
Coolant feed line ?	12	1
Hose clamp ?	11	3
Hose radiator ?	13	1
Bracket, coolant hose ?	15	1
Bracket, coolant hose ?	18	1
Bracket, coolant line ?	19	1
Coolant return line ?	21	1
Coolant return line ?	22	1
j. drawing - 17_1020 - Electric water pump / mounting		
Auxiliary water pump ?	1	1
Holder, electric coolant pump ?	2	1
Rubber band ?	3	1
k. drawing - 64_2155 - Heat exchanger		
Heat exchanger ?	1	1
Set pipe -	2	1
Installation kit, head exchanger ?	3	1
l. drawing - 64_2201 - Cooling water hoses		
Coolant hose feed 1	1	1
Coolant hose feed 2 ?	2	1
Coolant hose, return ?	3	1
Coolant hose, feed ?	4	1
Auxiliary water pump 2 ?	5	1
Combination bracket ?	6	1
Holder, auxiliary water pump ?	11	1
m. drawing - 66_0423 - Parking distance control		
Front Parking Sensors - black X	2	4
Front Parking Sensor ring <i>ren</i> /	3	6
Parking Sensors front sides - black ?	4	2
n. drawing - 66_0392 - Surround view		
Surround view camera - front ?	1	1
drawing - 63_1774 - Headlight		
Headlight, LED technology, left ?	1	1
Headlight, LED technology, right ?	1	1
drawing - 63_1798 - Fog lights		
Fog light, LED, left ?	1	1
Fog light, LED, right ?	1	1
o. drawing - 41_2573 - Bonnet/ mounted parts }		
Aluminium engine hood <i>bt</i> /	1	1
Left engine hood hinge X	2	1
Right engine hood hinge X	2	1
Lock left ?	6	1
Lock passive ?	6	1
Bowden cable ?	7,8	1
Lock top part ?	9	2
Holder, bonnet actuator ?	13	1
Gas-filled strut, engine-compartment lid ?	17	2
p. drawing - 41_2571 - bonnet seals		
Seal, engine bonnet, front X	1	1
Seal, bonnet, rear X	2	1
Gasket bonnet side left X	3	1
Gasket bonnet side right X	3	1
Sealing side panel, left X	4	1
Sealing side panel, right X	4	1
Upper left engine compartment cover <i>cm</i> /	7	1
Upper right engine compartment cover X	7	1
Stop buffer <i>ren</i> /	8	2
Stop buffer - on bonnet <i>ren</i> /	9	3

Remove and renew damaged parts
Cooling & AirCon Systems, Pipes & hoses, etc

[illegible]

Remove and renew damaged parts
Undercarriage works, arms, braces & bars

To straighten and realign, panel beat affected areas

Respray affected areas.

Front headlamp change & coding work

To flush cooling systems

To use machine flush and renewal with new oil and aircon reffridgerant

To re-fit tyres & balance wheel

To all under panels to aid job of changing exhaust downpipes,
full exhaust system

Using machine press to swap front wheel bearings

Computerised 4-Wheel Alignment

Rewiring of front parking sensors, surround camera.
Resetting of Error, Wiring for Reversing Camera & Sensors

1		500	\$ 1,500.00
1		X	\$ 1,000.00
1		750	\$ 1,200.00
1		100	\$ 400.00
		60	\$ 100.00
		80	\$ 150.00
2	\$ 30.00		\$ 60.00
1		80	\$ 100.00
2	\$ 80.00	X	\$ 160.00
1		80	\$ 100.00
1		100	\$ 400.00

PRICE BEFORE GST

ADD GST 7%

Grand Total:

\$ 9,470.00

\$ 662.90

\$ 10,132.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Raghu
Hp 900 10068

11 days

P/P

05/07/23

EXCESS: TBA

Raghu

Resurvey before
paint

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	030E
Vehicle Details	
Vehicle No.:	SLR5165M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2023
Vehicle Make:	B.M.W.
Vehicle Model:	530I LED NAV HUD MSPT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	13029999B48B20B
Chassis No.:	WBAJA52070WC07459
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$54,822.00
Original Registration Date:	17 Aug 2017
First Registration Date:	17 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$70,680.00
Enquire PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2027
PARF Rebate Amount:	\$49,476.00
Enquire COE Rebate Details	
COE Expiry Date:	16 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,802.00
COE Rebate Amount:	\$20,483.00
Total Rebate Amount:	\$69,959.00

The information contained herein is correct as at 05 Jul 2023

OK



BMW 5 Series 530i M-Sport

\$130,800 Instalment \$1,830/mth

PREMIUM AD

📄 Apply for 2.28% loan

♡ Shortlist

✔ Get Warranty

- Sell ur Car **for More Cash**
- Highest Price or **Get \$100 Free**

Overview

Financial

Photo

Research

Depreciation	ⓘ \$23,620 / year
Reg. Date	20-Jul-2017 (4yrs 14days COE left)
Manufactured	ⓘ 2017
Mileage	91,100 km (15.3k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	ⓘ \$1,210 / year
Power	185.0 kW (248 bhp)
Curb Weight	ⓘ 1,540 kg
COE	ⓘ \$50,001
OMV	ⓘ \$54,822
ARF	ⓘ \$70,680
Dereg Value	ⓘ \$69,682 as of today
No. of Owners	ⓘ 1

Type of Veh

Luxury Sedan