

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0032480
See Cheng Chai

Page: 1 of 1
Your ref.: TP-YP 7470A Lonpac
Job No.: 73747
Our ref.: 23.07.03
Payment
Date: 4/7/2023

Attn

Vehicle No: SCR 980R
Vehicle Model : Toyota Altis
Accident on ...: 1/7/2023

Not withstanding
1/1/2023
Resurvey After Paint
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear boot lid	852.90	25.00	<i>Ph</i> 639.68 ✓
1.00	Pc	Rear boot lid Toyota logo emblem	66.90	25.00	<i>Mr</i> 50.18 ✓
1.00	Pc	Rear boot lid Corolla emblem	53.20	25.00	<i>Mr</i> 39.90 ✓
1.00	Pc	Rear boot lid Altis emblem	54.29	25.00	<i>Mr</i> 40.72 ✓
1.00	Pc	Rear boot lid chrome outer trim	263.40	25.00	<i>Mr</i> 197.55 ✓
1.00	Pc	Rear boot lid reflector LH	377.60	25.00	283.20
1.00	Pc	Rear boot lid reflector RH	377.60	25.00	283.20
1.00	Pc	Rear bumper	423.50	25.00	<i>Bu</i> 317.63 ✓
Labour & Misc:					
1.00		To knock dents on rear end panel and renew of parts	450.00		450.00 <i>4000</i>
1.00		To spray paint (Pearl white)	550.00		550.00 <i>4800</i>

Sub-Total
GST 8.00%
Total

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

2 852.06
228.16
3 080.22

Acknowledged by Repairer

Signature:

Date:

司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."