

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0627/2023/EQ
DATE : 6-Jul-23
WIP : 27448

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/7/2023.

YOUR INSURED VEH NO : SFZ 7371 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. MICHAEL WONG TACK KEONG
ADDRESS : 50 MARINE PARADE ROAD
#10-13
SINGAPORE 449307
TELEPHONE : HP +65 94895248
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800114566-04
VEHICLE NO : **SKN 6767 C**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI
MODEL YEAR : 28/9/2018
ENGINE NO : DAX 035586
CHASSIS NO : WAUZZZF4J2156852
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jul-23
PLACE OF ACCIDENT : MCE TUNNEL TOWARDS ECP EXIT (P21M) EMERGENCY EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 6767 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.00 500	
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.		\$ 3,800.00 1500	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,952.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 6767 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 2,152.00	+
2	REAR BUMPER - LOWER	1	\$ 1,409.00	+
3	REAR BUMPER SPOILER	1	\$ 1,021.00	✓
4	REAR BUMPER TOW EYE COVER - LH	1	\$ 57.00	+
5	REAR BUMPER TOW EYE COVER - RH	1	\$ 34.00	+
6	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$ 228.00	+
7	REAR BUMPER CHROME TRIM - LH / RH	2	\$ 562.00	+
8	REAR BUMPER TAIL LIGHT - LH / RH	2	\$ 1,652.00	826
9	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00	+
10	REAR TAILGATE OPENING SENSOR LINE	1	\$ 129.00	+
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,104.00	+
12	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 7.00	+
13	REAR BUMPER HOLDING STRAP	1	\$ 201.00	+
14	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 200.00	+
15	REAR PARKING AID SENSOR - INNER / OUTER	3	\$ 815.00	+
16	REAR PARKING AID SEAL RING	4	\$ 11.00	+
17	PACKING ADHESIVE	1	\$ 22.00	+
18	AUDI EMBLEM	1	\$ 152.00	+
19	"Q5" INSCRIPTION	1	\$ 110.00	+
20	"TFSI" INSCRIPTION	1	\$ 110.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,467.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 6767 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	"QUATTRO" INSCRIPTION <i>At m</i>	1	\$ 110.00	<i>+</i>
22	REAR WHEEL COVER - LH / RH <i>m</i>	2	\$ 1,306.00	<i>✓</i>
23	SUNDRIES <i>?</i>		\$ 500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 12,383.00	
TOTAL LABOUR CHARGES		:	\$ 5,952.00	
GRAND TOTAL		:	\$ 18,335.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Adrian Lg*
: *21/07/23*

:
: *Not Authorised, 03 days*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT