



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23006744/Uvy3e2 Date: 25/07/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 1139T	Veh. Inspected	YN 2808D	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/1205	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	04/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU FVR34 (M)	c.c	7790	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JALFVR347B7000558	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	ANNAITE	5 mm	
L/H Front Tyre	275/70 R22.5	ANNAITE	5 mm	
R/H Rear Tyre	275/70 R22.5 (D)	ANNAITE	5/5 mm	
L/H Rear Tyre	275/70 R22.5 (D)	ANNAITE	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/06/2023	Inspection Date	11/07/2023	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 12 APR 2012 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	