

(08/11/13) wef

ASS. REC. BY: /

REF:

C96/AL5 230067571 CAP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims: _____

Sum Insured: _____ Excess: \$2,000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$113K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMY 5786 T Yr Regn: 15/3/2021

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Renault Grand Scenic cc 1461

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 183 630 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1RFA 00562894911

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 23/6/2023 D.O.A. 26/7/2023

Survey held at Desktop survey (Premier Auto)

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Net value \$74,190

Date/Time, File Pass to?

☐

: Preli. Report

1) Date/Time, File Return to?

☐

: Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

_____ S + RS, _____ SI

Photos

Others

TOTAL

Report Format : _____

Lum Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

> Back to OneMotoring

D.O.A. : 23/6/2023
Bal. : 7 yrs 8.6 mths.
M.V. = \$113,000,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	055D
Vehicle Details	
Vehicle No.:	SMY5786Y
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2023
Vehicle Make:	RENAULT
Vehicle Model:	GRAND SCENIC IV 1.5 DCI AT EU6
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	K9KF649D060095
Chassis No.:	VF1RFA00562894911
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$25,440.00
Original Registration Date:	15 Mar 2021
First Registration Date:	15 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$12,616.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2031
PARF Rebate Amount:	\$9,462.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,504.00
COE Rebate Amount:	\$29,343.00
Total Rebate Amount:	\$38,805.00

The information contained herein is correct as at 25 Jul 2023

OK

15,340

14,900

Premier Automotive Services Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat Carros Centre, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	23/06/2023
Vehicle Reg. No.:	SMY5786Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Vehicle Reg. Date:	15/03/2021
Vehicle Colour:	GREY		
Engine No:	K9KF649D060095	Chassis No:	VF1RFA00562894911
Odometer:	186630 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 5		

Present Location: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	17,199.83
Miscellaneous Items	164.00
Labour	2,160.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	19,523.83
- Excess (S\$)	2,000.00
(S\$)	17,523.83
+ GST 8.00% (S\$)	1,401.91
Nett Amount (S\$)	18,925.74

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2023)
Parts: M1-MPV	RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Premier Automotive Services Pte Ltd/SMY5786Y/05/07/2023 10:31	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	651004703R 23710373	*FRONT BONNET	0.00	0.00	*1,348.00 F	BUC
2	1	654000247R	*BONNET HINGE RH	0.00	0.00	*134.30 F	XNN
3	1	654013594R	*BONNET HINGE LH	0.00	0.00	*134.30 F	XNN
4	1	654704597R	*BONNET DAMPER LH	0.00	0.00	*112.20 F	XNN
5	1	654704597R	*BONNET DAMPER RH	0.00	0.00	*112.20 F	XNN
6	1	658408772R	*BONNET INSULATOR	0.00	0.00	*295.20 F	XNN
7	1	656016673R	*BONNET LOCK	0.00	0.00	*186.00 F	XNN
8	1	656220664R	*BONNET LOCK HANDLE	0.00	0.00	*75.10 F	XNN
9	1	623821034R	*RADIATOR GRILLE BLACK	0.00	0.00	*265.00 F	XNN
10	1	623855072R	*RADIATOR GRILLE CHROME MOULDING	0.00	0.00	*346.80 F	XNN
11	1	622561964R	*RADIATOR GRILLE	0.00	0.00	*473.80 F	XNN
12	1	620363937R	*FRONT RADIATOR GRILLE TOP GARNISH	0.00	0.00	*458.40 F	XNN
13	1	628905855R	*FRONT EMBLEM	0.00	0.00	*167.00 F	CRA
14	4	253A49995R	*FRONT PARKING SENSOR	0.00	0.00	*2,228.80 F	XNN
15	2	R284389618R	*BLIND SPOT SENSOR	0.00	0.00	*723.40 F	XNN
16	1	622568767R	*FRONT LOWER FLAP GUIDE INNER AIR DUCT	0.00	0.00	*251.60 F	XNN
17	1	628109433R	*RADIATOR GRILLE INNER AIR DUCT	0.00	0.00	*165.30 F	XNN
18	1	620223972R	*FRONT BUMPER	0.00	0.00	*1,676.20 F	BR
19	1	622540901R	*FRONT BUMPER LOWER LIP	0.00	0.00	*431.01 F	XNN
20	1	625005785R	*FRONT SUPPORT PANEL	0.00	0.00	*1,214.30 F	XNN
21	1	R752106346R	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*744.40 F	XNN
22	1	622907255R	*FRONT CENTRE BRACE BRACKET	0.00	0.00	*132.90 F	XNN
23	1	620901789R620906523	*FRONT BUMPER REINFORCEMENT LOWER GARNISH	0.00	0.00	*239.10 F	CRA
24	1	625300861R	*FRONT RADIATOR SUPPORT LOWER SUBFRAME	0.00	0.00	*707.20 F	XNN
25	1	261520089R	*FOGLAMP COVER LH	0.00	0.00	*261.40 F	XNN
26	1	261520089R	*FOGLAMP COVER RH	0.00	0.00	*261.40 F	XNN
27	1	261A24871R	*FOGLAMP CHROME MOULDING LH	0.00	0.00	*261.40 F	XNN
28	1	261A24871R	*FOGLAMP CHROME MOULDING RH	0.00	0.00	*261.40 F	XNN
29	1	261500097R	*HEADLAMP LH	0.00	0.00	*892.50 F	CRA
30	1	260101271R	*HEADLAMP RH	0.00	0.00	*892.50 F	XNN
31	1	240704528R	*FRONT BUMPER SENSOR HARNESS WIRE	0.00	0.00	*183.10 F	XNN

F=Franchise part.

Sub Total (\$\$)	15,636.21
+ Margin on L,N Items 10.00% (\$\$)	1,563.62
Total Parts (\$\$)	17,199.83

Premier Automotive Services Pte Ltd/SMY5786Y/05/07/2023 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	7	BUMPER CLIP	49.00 <i>NEC</i>
2	1	FRONT LICENSE PLATE WITH CASING	45.00 <i>OD</i>
3	10	FRONT RADIATOR TOP GARNISH CLIP	70.00 <i>?</i>
Sub Total (S\$)			164.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISMANTLE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT SUPPORT PANEL, AND ETC	New	1,000.00 <i>600</i>
2	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION	New	120.00 <i>50</i>
3	TO DISMANTLE & RENEW FRONT PARKING SENSOR & BLIND SPOT SENSOR	New	120.00 <i>50</i>
4	TO ALLY RUST PROOFING	New	120.00 <i>50</i>
5	TO RESPRAY FRONT BUMPER, FRONT BONNET, AND ETC	New	800.00 <i>500</i>
Gross Labour Cost (S\$)			2,160.00

Premier Automotive Services Pte Ltd/SMY5786Y/05/07/2023 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise.
- Excess = \$2,000k
- P/P or L/S repair?
- Resurvey before paint for P/P repair.
- Desktop survey done by Simon (62563561).

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: