

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM CHOON HOW
519 YIO CHU KANG RD
#04-75
SINGAPORE 787085

SURVEYOR COPY

Estimate No: MC1903592
Date: 27 Jun 2023
Policy No: DMPPHQ22-008326
Veh Reg No: SLU4091H
Make/Model: TOYOTA HARRIER G
GRADE

ATTN:

Your Ref No: SLU4091H
Claim Type: Third Party → Indic
Accident Date: 22/06/2023
TP Veh Reg No: SMZ1261R

*Not Withhold
Money After Part
1.B.1 2day*

Estimate Repair Cost to Vehicle No :SLU4091H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>✓</i> 904.00	<i>X</i>
2 REAR BUMPER CLIPS	12 PC	<i>na</i> 68.40	<i>X</i>
3 REAR BUMPER LOWER GARNISH	1 PC	<i>✓</i> 466.00	<i>✓</i>
4 REAR BUMPER REFLECTOR LH	1 PC	<i>✓</i> 77.20	<i>X</i>
5 REAR BUMPER SIDE RETAINER LH	1 PC	<i>✓</i> 92.60	<i>X</i>
6 REAR BUMPER SPONGE	1 PC	<i>✓</i> 142.80	<i>X</i>
7 REAR BUMPER SIDE SEAL LH	1 PC	<i>✓</i> 83.70	<i>X</i>
8 REAR BUMPER SIDE SEAL GROMMET	4 PC	<i>na</i> 24.80	<i>X</i>
9 REAR AIR VENT LH	1 PC	<i>✓</i> 231.50	<i>X</i>
10 REVERSE SENSOR OUTER LH	1 PC	<i>✓</i> 481.90	<i>X</i>
11 REVERSE SENSOR RING	4 PC	<i>na</i> 148.80	<i>X</i>
12 REVERSE SENSOR BKT	4 PC	<i>na</i> 161.80	<i>X</i>
		2,883.50	
	Less 25%	720.88	2,162.63
LABOUR			
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	<i>na</i> 60.00	<i>X</i>
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>m</i> 60.00	<i>X</i>
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>1501</i>
16 TO SPRAY REAR BUMPER,REAR END PANEL.	1 PC	500.00	<i>2201</i>
		1,120.00	1,120.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Zila
Ah Lim Motor Company