

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC6/A1423006765/Upe3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE1331M

at Workshop m/s 11u's Bn

of

Insured: SMU 2813T

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 826k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

196N
Vehicle: IN / OUT

Date: _____ Person Contacted: 279 10808

Veh No: GBE1331M Yr Regn: 04/09/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make: Toyota hie c.c 2982

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 316525 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P100159282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-115

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Austone

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/06/23 D.O.I. 6/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 115

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/7/23	4/5 @ 3300 Dep 11k in bond Susan

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Ref Date:

Ref No:

Vehicle No:

Model / Make:

Capacity: 2982 cc

05-07-2023

GBE1331M230626

GBE1331M

Toyota Hiace Van

Turbo 5 DR Manual

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Tailgate	\$ 2,051.60	1	\$ 2,051.60		✓
2		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	10 S/W
3		Tailgate "8 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	10 S/W
4		Tailgate Windscreen Sealant	\$ 50.00	1	\$ 50.00	SN	40 S/W
5		Tail Lamp Lh	\$ 386.40	1	\$ 386.40		✓
6		End Panel Outer	\$ 566.10	1	\$ 566.10		✓
7		End Panel Inner	\$ 936.20	1	\$ 936.20		✓
8		End Panel Sealant	\$ 50.00	1	\$ 50.00	SN	✓
9		Bumper	\$ 599.50	1	\$ 599.50		✓
10		Bumper Clips 1 set	\$ 65.00	1	\$ 65.00	SN	40 S/W
11		Bumper Bracket Lh	\$ 202.00	1	\$ 202.00		✓
12		Corner Panel Lh	\$ 165.80	1	\$ 165.80		✓
13		Corner Panel Bracket Lh	\$ 31.50	1	\$ 31.50		✓
14		Remove and refix rear tailgate components & wiper mechanism	(252)		\$ 80.00		60
15		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 800.00		500
16		To putty & spray painting & including touch up paint on accident affected areas			\$ 800.00		550
17		Remove & reinstall Windscreen Glass to facilitate repairs & perform water test			\$ 120.00		✓
18		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 40.00		✓

Total Parts & Labour of estimate for damaged vehicle

\$ 6,974.10

Total amount in Lumpsum Basis for repaired vehicle

\$ -

SDL

not Authorized
LH
merul
6/7/23
2/5# 3300
H days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Liu's Bro Auto Engrg Wks

P- 3686.6
252
2764.95
100
1270
4134.95
202
3907