

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

Not Withain

WS Ref: TP AIG
Claim Type: Third Party
Accident Date: 04/07/2023
TP Veh Reg No: SMP2138K

Repair B4 paint

4 days

Estimate No: ES2300683
Date: 05 Jul 2023
Policy No:
Veh Reg No: SMH3543J
Make/Model: HONDA FREED
1.5G
Chassis No: GB71082537
Engine No:
Reg. Date: 21/01/2019

Estimate Repair Cost to Vehicle No :SMH3543J

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	832.50	1 PC	832.50	7
2 REAR BUMPER CLIP	3.80	6 PCS	22.80	7
3 REAR TAILGATE	1,100.60	1 PC	1,100.60	7
4 TAILGATE LOGO	41.80	1 PC	41.80	7
5 TAILGATE EMBLEM- FREED	55.00	1 PCS	55.00	7
6 TAILGATE EMBLEM - HYBRID	75.10	1 PC	75.10	7
7 TAILGATE INNER LOCK	197.80	1 PC	197.80	7
8 REAR WINDSCREEN GLASS MOULDING	152.10	1 PC	152.10	7
			2,477.70	
		Less 20%	495.54	1,982.16
Special Net				
9 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	7
10 REAR TAILGATE BODY PROTECTOR	120.00	1 PC	120.00	7
			160.00	160.00
Labour				
11 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	7
12 TO REMOVE AND REFIX REAR BUMPER, TAILGATE, LOCK ASSY, REFLECTOR, KNOCK AND REPAIR REAR PANEL AND RE-ALIGN TO SAME	500.00	1 LA	500.00	7
13 TO PUTTY AND RESPRAY ON REAR PANEL, TAILGATE, REAR BUMPER	700.00	1 LA	700.00	7
14 TO REMOVE AND REFIX REVERSE CAMERA, BUZZER ASSY, SMART AND REST SYSTEM	40.00	1 LA	40.00	7
15 RUSTPROOFING	30.00	1 LA	30.00	7
			1,390.00	1,390.00
		Total	S\$ 3,532.16	
		Add GST @ 8%	282.57	
		Total Amount Payable	S\$ 3,814.73	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification/s is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE