

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mrs Tan Pei Ming Grace 261 Toa Payoh East #11-06 Singapore 310261 Mobile: 97867603
	Document No. 0	
	Document Date 07/07/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGZ15R	AWTLTQ F3	24/05/2017	SLN9879G	0	22782	61TP/SLN9879G/010723
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTJBARBZ602133255	8ARW552782	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: INDIA INT'L ACC DATE: 01.07.2023 T/P VEH: SML2037P DATE IN: DATE SURVEY: DATE AUTHORIZE:				50 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL, TAILGATE AND FIX NEW PARTS				1920 3840.00
3	B	BP-RES3 TO SPRAY PAINT ON REAR BUMPER, REAR PANEL, TAILGATE AND ROOF SPOILER				1632 4080.00
4	B	BP-LAB3 TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				240.00
5	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR LUGGAGE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT)				? 480.00

Resu
4p 90010068
6 days
07/07/23
Recy 64 part

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mrs Tan Pei Ming Grace 261 Toa Payoh East #11-06 Singapore 310261 Mobile: 97867603		
			Document No. 0				
			Document Date 03/07/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGZ15R	AWTLTQ F3	24/05/2017	SLN9879G	0	22782	61TP/SLN9879G/010723
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBARBZ602133255		8ARW552782	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
6	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)				240.00	
7	B	BP-LAB3 TO REMOVE AND TRANSFER ROOF SPOILER TO NEW TAILGATE (NETT)				240.00	
8	B	BP-LAB3 TO REMOVE AND TRANSFER TAILGATE COMPONENT AND MECHANISM TO NEW TAILGATE (NETT)				960.00	
9	Z	BP-SLANT SUPPLY TAILGATE SEALANT (NETT)				100.00	
10	B	BP-LAB3 TO RMEOVE AND TRANSFER REAR REVERSE CAMERA TO NEW TAILGATE (NETT)				240.00	
11	B	BP-WS3 TO REMOVE AND REPLACE REAR WINDSCREEN GLASS (NETT)				960.00	
12	S	BP-SUBLET REPLACE REAR WINDSCREEN GLASS SOLAR FILM (NETT)				480.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mrs Tan Pei Ming Grace 261 Toa Payoh East #11-06 Singapore 310261 Mobile: 97867603		
			Document No. 0				
			Document Date 03/07/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGZ15R	AWTLTQ F3	24/05/2017	SLN9879G	0	22782	61TP/SLN9879G/010723
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTJBARBZ602133255		8ARW552782	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)				240.00	
14	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
15	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.					
16	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00	
17	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
18	3	L52159-78918 COVER, RR BUMPER	1.00	868.70		868.70	
19	4	L52169-78010 COVER, RR BUMPER,	1.00	578.60		578.60	
20	5	L50768-78010 COVER SUB-ASSY, RR	1.00	320.80		320.80	
21	6	L52592-78010 SEAL, RR BUMPER ?	1.00	110.80		110.80	
22	7	L52591-78010 SEAL, RR BUMPER ?	1.00	110.80		110.80	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details													
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mrs Tan Pei Ming Grace													
			Document No. 0		261 Toa Payoh East #11-06 Singapore 310261													
			Document Date 03/07/2023		Mobile: 97867603													
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks											
2017	AGZ15R	AWTLTQ F3	24/05/2017	SLN9879G	0	22782	61TP/SLN9879G/010723											
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On											
JTJBARBZ602133255		8ARW552782	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00											
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount										
23	8	L52171-78010	REINFORCEMENT, RR ?			1.00	1112.70		1112.70									
24	9	L52016-78010	ARM SUB-ASSY, RR ?			1.00	189.30		189.30									
25	0	L52015-78010	ARM SUB-ASSY, RR ?			1.00	189.30		189.30									
26	1	L52156-78010	SUPPORT, RR BUMPER ?			1.00	124.40		124.40									
27	2	L52155-78010	SUPPORT, RR BUMPER ?			1.00	124.40		124.40									
28	3	L52162-78901	PLATE, RR BUMPER ?			1.00	7.20		7.20									
29	4	L75392-35220	RETAINER, OUTSIDE ?			1.00	5.20		5.20									
30	5	L68105-78040	GLASS SUB-ASSY, BACK ?			1.00	1715.80		1715.80									
31	6	L67005-78050	PANEL SUB-ASSY, BACK ?			1.00	4158.80		4158.80									
32	7	L75443-78020	PLATE, BACK DOOR ?			1.00	101.80		101.80									
33	8	L90975-02212	EMBLEM, SYMBOL ?			1.00	82.10		82.10									
34	9	L75444-78010	PLATE, BACK DOOR ?			1.00	87.50		87.50									
35	0	L89341-78010 B2	SENSOR, ULTRASONIC, ?			2.00	582.70		1165.40									
36	1	L69321-78020	COVER, BACK DOOR ?			1.00	48.50		48.50									
37	2	L69350-48063	LOCK ASSY, BACK DOOR ?			1.00	1016.30		1016.30									
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					Charge Summary <table border="1"> <tr> <td>Parts</td> <td>12,534.40</td> </tr> <tr> <td>Labour</td> <td>11,720.00</td> </tr> <tr> <td>Sublet</td> <td>480.00</td> </tr> <tr> <td>Lubrication/Fluid</td> <td>0.00</td> </tr> <tr> <td>Others</td> <td>0.00</td> </tr> </table>		Parts	12,534.40	Labour	11,720.00	Sublet	480.00	Lubrication/Fluid	0.00	Others	0.00	Total 24,734.40 GST 8.00% 1,978.75 Less 0.00 Amount Due 26,713.15	
Parts	12,534.40																	
Labour	11,720.00																	
Sublet	480.00																	
Lubrication/Fluid	0.00																	
Others	0.00																	

Customer Copy