

Not Authored
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB9810P

AAD2307-002

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

05 JUL 2023

SHB9810P

JTDKB3FU803091340

200303878K

TOYOTA

PRIUS GEN 4

3/7/2023

YP885H/LONPAC

21/8/2020

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 BOARD, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2

\$	Bu	612.68	—
\$	Pr	27.93	X
\$	nd / Cr	472.19	—
\$	Pr	149.21	X
\$	Pr	149.21	X
\$	Pr	167.48	X
\$	Pr	167.48	X
\$		419.90	?
\$	Pr	49.25	}
\$	Pr	49.25	
\$	Pr	88.41	
\$	Pr	428.19	
\$	Pr	329.49	
\$	Pr	88.41	
\$	Pr	428.19	
\$	Pr	329.49	
\$	Pr	220.50	
\$	Pr	304.92	
\$	Pr	290.43	
\$	Pr	159.39	
\$	Pr	824.46	}
\$	Pr	1,443.86	
\$	Pr	284.55	
\$	Pr	65.73	
\$	Pr	305.66	
\$	Pr	305.66	
\$	Pr	77.18	
\$	Pr	77.18	}
\$	Pr	1,156.89	
\$	Pr	68.88	

Trans-cab Auto Services Pte Ltd**AAD2306-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB9810P

- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

	\$	<i>nn</i>	68.88	X
	\$	<i>nn</i>	90.30	X
TOTAL	\$		9,701.23	
25%	\$		2,425.31	
	\$		7,275.92	

SPECIAL NETT**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

	\$	<i>nn</i>	700.00	X
	\$	<i>nn</i>	65.00	<i>60111</i>
	\$	<i>nn</i>	60.00	X
	\$	<i>nsp</i>	180.00	X
	\$	<i>nn</i>	150.00	X
	\$	<i>nn</i>	200.00	X
	\$	<i>nn</i>	130.00	X
TOTAL	\$		1,485.00	
TOTAL PARTS	\$		8,760.92	

LABOUR

To rust-proofing of the affected areas.

\$ *nn* 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 *2201*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *2001*

To transfer of tailgate fittings and conduct water seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 170.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB9810P

AAD2306-

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

TOTAL \$ 5,250.00

OVERALL TOTAL \$ 14,010.92

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: