



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

18/7/2023

Survey Details:

Date of loss	26-Jun-23
Date of appointment	5-Jul-23
Date of survey	5-Jul-23
Location of survey	WAH YU AUTOMOTIVE BODY WORK

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SMZ 7782P
Make and Model	MERCEDES BENZ E200 (A)
Date of registration	19/9/2014
Excess	
Market Value	\$ 50,000.00
Part Rebate	\$ 35,355.00
Nett Loss	\$ 14,645.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>4</u>
----------------------------------	-----------------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$3,500.00 - \$4,500.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	