

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 6213L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED/ DEFORMED	1,130.00	866.00
1	FRONT BUMPER RETAINER LH	NECESSARY	38.00	38.00
1	FRONT BUMPER RETAINER RH	NECESSARY	38.00	38.00
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	64.00	-
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	64.00	-
1	FRONT HEADLAMP LH	NOT NECESSARY	2,750.00	-
1	FRONT HEADLAMP RH	NOT NECESSARY	2,750.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	358.00	-
1	FRONT GRILLE ASSY	NOT NECESSARY	890.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	55.00	-
1	FRONT BUMPER LOWER GRILLE	TWISTED	189.00	189.00
1	FRONT FOG LAMP LH	NOT NECESSARY	485.00	-
1	FRONT FOG LAMP RH	NOT NECESSARY	485.00	-
1	FRONT FOG LAMP COVER LH	NOT NECESSARY	155.00	-
1	FRONT FOG LAMP COVER RH	NOT NECESSARY	155.00	-
	LESS 20% DISCOUNT		-1,921.20	-226.20
			7,684.80	904.80
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT NUMBER PLATE (SN)	BENT	100.00	40.00
			190.00	70.00
	<u>LABOUR</u>			
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		100.00	20.00
	PANEL BEATING ON AFFECTED AREA AND RENEW PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	200.00

Report Ref No. CS/UOI23006813/Unp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			1,300.00	420.00
	GRAND TOTAL		9,174.80	1,394.80

RECOMMENDED COST OF LUMP SUM REPAIRS		1,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI23006813/Unp3m4

CHUA KANG SENG

Licensed Appraiser