

Name &amp; Address:

**Motor Claims Department**  
**Sompo Insurance Singapore Pte Ltd**  
 8 Temasek Boulevard  
 #04-01 Suntec Tower 3  
 Singapore 038988

Vehicle No:

**SNL7788K**

Date:

03.07.2023

Brand &amp; Model:

BMW

Franchise:

EAPL - BMW

Email/Fax No:

Contact No:

Chassis/VIN No:

**WBA62EG0605V79390**

Contact Person (Eurokars):

EDWIN/ERIC

Type of Claim:

YEAR MODEL:

WIP#:

**14642**

Contact No (Eurokars):

6331 0648

THIRD PARTY

15/07/1905

**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	Plastic cap	B07.14.7.169.847	8		-	\$ 6.80
2	Expanding nut	B07.14.7.201.307	16		-	\$ 15.20
3	Plug in retainer	B07.14.7.376.600	1		-	\$ 2.40
4	Left rear side panel	B41.30.5.A52.CB7	1		-	\$ 1,937.20
5	Reinforcement	B41.30.5.A58.AE1	1		-	\$ 98.65
6	Reinforcement	B41.30.5.A58.AE3	1		-	\$ 98.65
7	Reinforcement	B41.30.5.A58.AE5	1		-	\$ 98.65
8	Door rear Left	B41.52.5.A38.655	1		-	\$ 1,326.95
9	Expanding Rivet	B51.16.1.881.149	8		-	\$ 3.60
10	Plastic cap	M51.16.1.943.122	8		-	\$ 6.80
11	Clip	B51.33.7.140.714	14		-	\$ 14.00
12	Window Guide	B51.35.9.451.547	1		-	\$ 144.85
13	Door wheather strip (gasket)	B51.76.5.A63.761	1		-	\$ 195.10
14	Body wheather strip (Gasket)	B51.76.9.450.461	1		-	\$ 157.15
15	Expanding Rivet	B51.77.7.171.004	8		-	\$ 11.20
16	Protective film for tail light	B63.21.5.A4C.4F0	1		-	\$ 3.50
17	Tail Light LH	B63.21.9.465.351	1		-	\$ 520.15
18	Cavity Protection	B83.12.0.390.086	1		-	\$ 21.25
19	Blind Rivet	B83.19.0.301.421	8		-	\$ 4.40
20	Screw	B83.19.0.301.639	3		-	\$ 1.95
21	Cleaner R2	B83.19.0.417.324	1		-	\$ 15.50
22	Punch Rivet	B83.19.2.158.079	28		-	\$ 16.80
23	Body Adhesive	B83.19.2.158.654	1		-	\$ 131.90
24	Blind Rivet	B83.19.2.158.655	1		-	\$ 0.60
25	Cleaner R1	B83.19.2.211.217	1		-	\$ 30.05
26	Punch Rivet	B83.19.2.457.307	19		-	\$ 11.40
27	Body Adhesive	B83.19.5.A59.935	1		-	\$ 380.50
28	Sealant D2	B83.42.5.A54.7B9	1		-	\$ 32.10

Sub-Total (Parts Price) \$ - \$ 5,287.30

**LABOUR / SERVICES CHARGES**

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE LH REAR FENDER, LH REAR DOOR & ALL OTHER NECESSARY PARTS, INCLUDE THE REMOVAL & REINSTALLATION OF RHR QUARTER GLASS, DOOR COMPONENTS, WINDOW MECHANISM WHEEL ARCH, TAIL LIGHTS, REAR BUMPER ETC TO FACILITATE REPAIRS		\$ 7,488.00

2	SPRAY PAINTING OF NEW LH REAR FENDER & LH REAR DOOR		\$ 2,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
39	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
40	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 200.00
42	SUNDRIES.	nett	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	-	\$	10,588.00
		<b>REVISED</b>		<b>PRICE</b>
Parts Price	\$	-	\$	5,287.30
Labour Price	\$	-	\$	10,588.00
Total (Initial Estimate)	\$	-	\$	15,875.30
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	15,875.30
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	15,875.30
GST	8%	\$	-	\$ 1,270.02
<b>GRAND TOTAL</b>	\$	-	\$	<b>17,145.32</b>