

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Jul 2023

Preliminary Advice

Vehicle No	: SNL7788K	Accident Date	: 19/06/2023
Make	: BMW X1	Policy No.	: DMPG23006805
Assignment Date	: 10/07/2023	Excess	: S\$0.00
Date of Inspection	: 6/7/2023	Est. Duration of Repair	: 6
Inspection At	:EUROKARS HABITAT PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,875.30
Revised Amount	:S\$	10,352.30
Check Items (Estimated)	:S\$	520.15
Total	:S\$	10,872.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	220,000.00
COE / PARF Rebate	:S\$	132,816.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,184.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .