



Name & Address:

Motor Claims Department  
**ERGO Insurance Pte. Ltd.**  
 8 Temasek Boulevard  
 #04-01 Suntec Tower 3  
 Singapore 038988

Vehicle No:

**SNL7788K**

Date:

03.07.2023

Brand & Model:

**BMW**

Franchise:

EAPL - BMW

Email/Fax No:

Contact No:

Chassis/VIN No:

**WBA62EG0605V79390**

Contact Person (Eurokars):

EDWIN/ERIC

Type of Claim:

**THIRD PARTY**

YEAR MODEL:

**15/07/1905**

WIPR:

**14642**

Contact No (Eurokars):

6331 0648

### PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	Plastic cap <i>N /</i>	B07.14.7.169.847	8		-	\$ 6.80
2	Expanding nut <i>N /</i>	B07.14.7.201.307	16		-	\$ 15.20
3	Plug in retainer <i>N /</i>	B07.14.7.376.600	1		-	\$ 2.40
4	Left rear side panel <i>SN /</i>	B41.30.5.A52.CB7	1		-	\$ 1,937.20
5	Reinforcement <i>N /</i>	B41.30.5.A58.AE1	1		-	\$ 98.65
6	Reinforcement <i>N /</i>	B41.30.5.A58.AE3	1		-	\$ 98.65
7	Reinforcement <i>N /</i>	B41.30.5.A58.AE5	1		-	\$ 98.65
8	Door rear Left <i>SN /</i>	B41.52.5.A38.655	1		-	\$ 1,326.95
9	Expanding Rivet <i>N /</i>	B51.16.1.881.149	8		-	\$ 3.60
10	Plastic cap <i>N /</i>	M51.16.1.943.122	8		-	\$ 6.80
11	Clip <i>N /</i>	B51.33.7.140.714	14		-	\$ 14.00
12	Window Guide <i>X</i>	B51.35.9.451.547	1		-	\$ 144.85
13	Door weather strip (gasket) <i>N /</i>	B51.76.5.A63.761	1		-	\$ 195.10
14	Body weather strip (Gasket) <i>N /</i>	B51.76.9.450.461	1		-	\$ 157.15
15	Expanding Rivet <i>N /</i>	B51.77.7.171.004	8		-	\$ 11.20
16	Protective film for tail light <i>N /</i>	B63.21.5.A4C.4F0	1		-	\$ 3.50
17	Tail Light LH <i>?</i>	B63.21.9.465.351	1		-	\$ 520.15
18	Cavity Protection <i>N /</i>	B83.12.0.390.086	1		-	\$ 21.25
19	Blind Rivet <i>N /</i>	B83.19.0.301.421	8		-	\$ 4.40
20	Screw <i>N /</i>	B83.19.0.301.639	3		-	\$ 1.95
21	Cleaner R2 <i>N /</i>	B83.19.0.417.324	1		-	\$ 15.50
22	Punch Rivet <i>N /</i>	B83.19.2.158.079	28		-	\$ 16.80
23	Body Adhesive <i>N /</i>	B83.19.2.158.654	1		-	\$ 131.90
24	Blind Rivet <i>N /</i>	B83.19.2.158.655	1		-	\$ 0.60
25	Cleaner R1 <i>N /</i>	B83.19.2.211.217	1		-	\$ 30.05
26	Punch Rivet <i>N /</i>	B83.19.2.457.307	19		-	\$ 11.40
27	Body Adhesive <i>N /</i>	B83.19.5.A59.935	1		-	\$ 380.50
28	Sealant D2 <i>N /</i>	B83.42.5.A54.7B9	1		-	\$ 32.10

Sub-Total (Parts Price) \$ - \$ 5,287.30

### LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE LH REAR FENDER, LH REAR DOOR & ALL OTHER NECESSARY PARTS, INCLUDE THE REMOVAL & REINSTALLATION OF RHR QUARTER GLASS, DOOR COMPONENTS, WINDOW MECHANISM WHEEL ARCH, TAIL LIGHTS, REAR BUMPER ETC TO FACILITATE REPAIRS <i>C88044</i>	<i>3360</i>	\$ <del>788.00</del>

**REPAIR ESTIMATE**

2	SPRAY PAINTING OF NEW LH REAR FENDER & LH REAR DOOR @850/2	1600	\$	2,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	250	\$	<del>350.00</del>
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$	<del>250.00</del>
39	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$	250.00
40	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$	<del>200.00</del>
42	SUNDRIES.	nett	\$	<del>20</del> 50.00

Survey Date & Time: 07/07/23 0142w Repair Days: 6 days Excess: TBA

Surveyor Remarks: *Person - Heq...  
person  
Rey by part*

Remarks:  
 • This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.  
 • A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	-	\$	10,588.00
			<u>REVISED</u>	<u>PRICE</u>
Parts Price	\$	-	\$	5,287.30
Labour Price	\$	-	\$	10,588.00
Total (Initial Estimate)	\$	-	\$	15,875.30
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	15,875.30
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	15,875.30
GST	8%	\$	-	\$ 1,270.02
<b>GRAND TOTAL</b>	\$	-	\$	<b>17,145.32</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	789B
Vehicle No.:	SNL7788K
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2023
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE16 MSPT ALED
Primary Colour:	Grey
Manufacturing Year:	2022
Engine No.:	F081P196B38A15P
Chassis No.:	WBA62EG0605V79390
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$37,567.00
Original Registration Date:	12 May 2023
First Registration Date:	12 May 2023
Transfer Count:	0
Actual ARF Paid:	\$44,594.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2033
PARF Rebate Amount:	\$33,445.00
COE Expiry Date:	11 May 2033
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$101,001.00
COE Rebate Amount:	\$99,371.00
<b>Total Rebate Amount:</b>	<b>\$132,816.00</b>

The information contained herein is correct as at 09 Jul 2023

OK



# BMW X1 sDrive16i M-Sport

**\$228,888** Instalment \$1,976/mth

PREMIUM AD

Apply for 2.28% loan

Shortlist

Loan Calculator

mycarforum

Singapore Reckless Drivers

TRENDING DISCUSSIONS

Part XIV

READ MORE >

Overview Financial Photo Research

Depreciation	<i>i</i> \$21,730 / year
Reg. Date	19-Jan-2023 (9yrs 6mths 9days COE left)
Manufactured	<i>i</i> 2022
Mileage	757 km
Transmission	Auto
Engine Cap	1,499 cc
Road Tax	<i>i</i> \$684 / year
Power	90.0 kW (120 bhp) View specs of the <a href="#">BMW X1</a>
Curb Weight	<i>i</i> 1,500 kg
COE	<i>i</i> \$86,000
OMV	<i>i</i> \$36,645
ARF	<i>i</i> \$43,303
Dereg Value	<i>i</i> \$114,495 as of today
No. of Owners	<i>i</i> 1