

Name & Address:
Motor Claims Department
Allianz Insurance Sinagpre Pte Ltd
79 Robinson Road
#09-01
Singapore 068897
Email/Fax No:

Vehicle No:
SNJ6866K
Brand & Model:
BMW IX3
Chassis/VIN No:
WBY42DU0X0S496165

Date:
03.07.2023
Franchise:
EAPL BMW
Contact Person (Eurokars):
EDWIN/ERIC
Contact No (Eurokars):
6331 0648

Type of Claim: THIRDPARTY
YEAR MODEL: 15/07/1905

WIP#: 14603

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	Combination screw <i>me</i>	B07.14.7.263.985	4			\$ 15.30
2	Hex Nut <i>me</i>	B07.14.7.266.441	4			\$ 13.20
3	C-clip <i>me</i>	B07.14.7.311.312	8			\$ 9.60
4	Expanding rivets <i>me</i>	B07.14.7.401.727	10			\$ 26.50
5	Hex Bolt <i>me</i>	B07.14.9.311.623	4			\$ 20.40
6	Trunk Lid <i>BT</i>	B41.00.7.494.942	1			\$ 2,154.70
7	Bumper Trim (rear) <i>de</i>	B51.12.5.A47.A34	1			\$ 1,597.60
8	Lower Trim (glossy black) ?	B51.12.5.A47.A49	1			\$ 298.50
9	Gasket <i>me</i>	B51.12.7.400.673	2			\$ 12.20
10	Cover RH (Black Glossy -Vertical pos) X	B51.12.8.081.888	1			\$ 80.30
11	Rear bumper carrier ?	B51.12.8.498.641	1			\$ 816.15
12	Bumper Mount LH X	B51.12.9.850.833	1			\$ 130.50
13	Bumper Mount RH <i>de</i>	B51.12.9.850.834	1			\$ 130.50
14	Bumper Cover Lower part ?	B51.12.9.850.837	1			\$ 278.85
15	Absorber Left <i>me</i> X	B51.12.9.850.845	1			\$ 52.05
16	Adopter for bumper and lower part ?	B51.12.9.850.847	1			\$ 178.55
17	Bottom cover LH X	B51.12.9.850.849	1			\$ 89.25
18	Bottom cover RH ?	B51.12.9.850.850	1			\$ 89.25
19	Mount for bumper LH X	B51.12.9.853.315	1			\$ 230.55
20	Mount for bumper RH ?	B51.12.9.853.316	1			\$ 230.55
21	Grommet for Badge <i>me</i>	B51.14.1.807.495	2			\$ 1.90
22	Badge <i>me</i>	B51.14.5.A26.938	1			\$ 74.35
23	Emblem (M at side panel) X	B51.14.8.058.881	1			\$ 85.50
24	Logo iX3 <i>me</i>	B51.14.9.463.062	1			\$ 100.35
25	Rear Glass windshield <i>me</i>	B51.31.7.483.079	1			\$ 1,107.25
26	Reflector LH X	B63.14.8.083.833	1			\$ 41.80
27	Reflector RH ?	B63.14.8.083.834	1			\$ 41.80
28	Washer plastic for tail light <i>me</i>	B63.21.7.457.464	2			\$ 6.30
29	Gasket set for rear light <i>me</i>	B63.21.7.467.918	1			\$ 39.55
30	Rear light side panel LH X	B63.21.9.463.048	1			\$ 624.20
31	Rear Light LH X	B63.23.9.463.054	1			\$ 436.95
32	Third Brake light +	B63.25.7.426.511	1			\$ 273.50
33	Adhesive for Rear windshield <i>me</i>	B83.19.2.289.285	1			\$ 131.55
34						

Sub-Total (Parts Price) \$ 9,420.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE REAR BUMPER, REAR LID AND ALL THE CONNECTING PARTS RELATED TO ACCIDENT <i>0840x2</i>	<i>1680</i>	\$ 2,496.00
2	SPRAY PAINT REAR BUMPER & REAR LID <i>epw x2</i>	<i>1600</i>	\$ 2,000.00
3	REPLACING OF REAR WINDSCREEN	NETT	\$ 600.00
4	SUPPLY & INSTALL SOLAR FILM FOR REAR WINDSCREEN	NETT	\$ 280.00
39	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150</i>	\$ 250.00
40	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 200.00
42	SUNDRIES.	nett	\$ 20 <i>58.00</i>

Survey Date & Time: <i>07/07/23 @ 1400</i>	Repair Days: <i>5 days</i>	Excess:
---	-------------------------------	---------

Surveyor Remarks:

*Repair - 4p 90010068
Resin before paint*

Sub-Total (Labour Price) \$ - \$ 5,876.00

	REVISED	PRICE
Parts Price	\$ -	\$ 9,420.00
Labour Price	\$ -	\$ 5,876.00
Total (Initial Estimate)	\$ -	\$ 15,296.00
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 15,296.00
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 15,296.00
GST 8%	\$ -	\$ 1,223.68
GRAND TOTAL	\$ -	\$ 16,519.68

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: