

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg No. 197401559W GST Reg No M2-0020081-x
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1766473	Page No. : 1 of 2
Date IN : 23/05/2023	Invoice Number : 2672936 / WSB
Motor Claim Advisor: Jack Ng Guo Ming	Invoice Date : 21/06/2023
	Payment Terms : 30 Days From Invoice
	Invoice By : Mahamod Bin Mohd Sanif

- CUSTOMER INFORMATION -	- INVOICE TO - 85
Mr Lam Kee Siong Terence	Liberty Insurance Pte Ltd
11 Jalan Mutiara	51 Club Street
#06-01	#03-00 Liberty House
Singapore 249191	Singapore 069428

REGN. NO. SKH8811B	CHASSIS NO. WBA4H32080BH12043	REGN. DATE 31/10/2017	MODEL 420IA GC	MILEAGE 66180
------------------------------	---	---------------------------------	--------------------------	-------------------------

<u>LABOUR 1</u>		NETT
To replace front bumper and attachment parts.		850.00
To respray front bumper.		1,038.00
To replace right headlight.		481.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.		177.00
Sundries.		80.00
INS CLAIMS : ACCIDENT REPAIR. OD CLAIMS.		0.00
DATE OF ACCIDENT :17.05.2023. POLICY NO :SD22V06400.		
YOUR REF NO :AVS23/1588-OD-PK. OIC:POH KHIM		
PAPER SURVEY BY THINH FROM LIBERTY ON 22.05.2023.		
AUTHORISED BY THINH VIA EMAIL ON 22.05.2023.		
UNINSURED LOSSES HANDLED BY T.A AGAINST POLICE INVEST		0.00
3RD PARTY CAR :QX1874K. INSURANCE EXCESS = \$972.00		
PROPOSE LOSS OF USE = \$259.20 LOU:\$ 129.60 AS MCA REQUEST.		
	\$100	
Total Labour 1:		2,626.00
<u>PARTS</u>		NETT
	Retail	
	Qty Price	
FRT BUMPER PANEL PRIMED (LINES)	1 1,084.65	1,084.65
SET MOUNTING PDC/PMA SENSOR FRT	1 81.35	81.35
RH HEADLIGHT LED TECHNOLOGY	1 2,808.05	2,808.05
(DG/SL) ADHESIVE SET K6	1 53.05	53.05
RH PARTIALLY OPEN GRID (SPORT/LUXUR	1 91.00	91.00
RH TRIM SPORT LINE	1 127.40	127.40
PLAQUE 82MM	1 72.85	72.85
Total Parts :		4,318.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax 64796601 (AfterSales)
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : B1 1766473	Page No. : 2 of 2
Date IN : 23/05/2023	Invoice Number : 2672936 / WSB
Motor Claim Advisor: Jack Ng Guo Ming	Invoice Date : 21/06/2023
	Payment Terms : 30 Days From Invoice
	Invoice By : Mahamod Bin Mohd Sanif

Labour Charges : 2,546.00	Total Labour & Parts Charges : S\$ 6,944.35
Parts Charges : 4,318.35	Less Insurance Excess : S\$ 900.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 6,044.35
	GST @ 8% : S\$ 483.55
	Invoice Total Amount Include GST : S\$ 6,527.90

Computer generated invoice. No signature is required. **Amount Payable Include GST : S\$ 6,527.90**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

1766473

Estimate No. : b1 66050	Page No. : 1 of 5
Date Estimated : 19/05/2023	
Prepared By : Jack Ng Guo Ming	

- ESTIMATE REPAIR FOR - Lam Kee Siong Terence 11 Jalan Mutiara #06-01 Singapore 249191	- ACCOUNT - 85 Liberty Insurance Pte Ltd 51 Club Street #03-00 Liberty House Singapore 069428
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH8811B	WBA4H32080BH12043	31/10/2017	420ia GC	64193

DESCRIPTION	VALUE		
To replace front bumper, make good right fender and all damage attachment ✓ 850	2,550.00		
To respray front bumper and right front fender ✓ 1038	1,923.00		
To replace right headlight ✓ 481	481.00		
To check electrical wiring system at the front section for proper function including adjustment of headlights. ✓ 177	177.00		
Sundries. ✓ 80	150.00		
Total Labour 1:			
** KINDLY PROVIDE MILEAGE PHOTO AND CHASSIS NUMBER PHOTO **			
5,281.00			
DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TOP CARRIER ?	1	432.00	432.00
FRT SHOCK ABSORBER ?	1	65.10	65.10
LH FOG LAMP SUPPORT ?	1	79.10	79.10
RH FOG LAMP SUPPORT ?	1	79.10	79.10
COVER LOWER PART CENTRE ?	1	46.05	46.05
RH PARTIALLY OPEN GRID (SPORT/LUXUR ✓ cut	1	91.00	91.00
RH TRIM SPORT LINE ✓ cut	1	127.40	127.40
FINISHER ROD CENTRE (SPORT LINE) ?	1	55.75	55.75
INSERT AIR INLET MIDDLE (LINES) ?	1	151.70	151.70
FRT BUMPER PANEL PRIMED (LINES) X repair	1	1,084.65	1,084.65
FRT BUMPER LOWER MOUNT ?	1	139.15	139.15
RH HEADLIGHT LED TECHNOLOGY ✓ cut	1	2,808.05	2,808.05
Total Parts :			5,159.05

OD PAPER SURVEY DATE: 22/05/2023
WITHOUT PREJUDICE
THINH NGUYEN - TEL/WHATSAPP: (+84) 909 232 062
CLAIM NO: AVS23/1588
OFFICER: MS POH KHIM
EXCESS: TBA
WORKING DAYS: 3 DAYS
** REQUIRED MILEAGE PHOTO, CHASSIS NUMBER PHOTO, CHECK ITEMS APPROVAL BEFORE PROCEED AND BEFORE PAINT PHOTO**
FINALIZATION WILL SUBJECT TO PART PRICE AND PHOTO PROVIDED

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 66050	Page No. : 1 of 5
Date Estimated : 19/05/2023	
Prepared By : Jack Ng Guo Ming	

- ESTIMATE REPAIR FOR - Lam Kee Siong Terence 11 Jalan Mutiara #06-01 Singapore 249191	- ACCOUNT - 85 Liberty Insurance Pte Ltd 51 Club Street #03-00 Liberty House Singapore 069428
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH8811B	WBA4H32080BH12043	31/10/2017	420ia GC	64193

DESCRIPTION	VALUE		
To replace front bumper, make good right fender and all damage attachment ✓ 850	2,550.00		
To respray front bumper and right front fender ✓ 1038	1,923.00		
To replace right headlight. ✓ 481	481.00		
To check electrical wiring system at the front section for proper function including adjustment of headlights. ✓ 177	177.00		
Sundries. ✓ 80	150.00		
Total Labour 1:	5,281.00		
** KINDLY PROVIDE MILEAGE PHOTO AND CHASSIS NUMBER PHOTO **			
DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TOP CARRIER ?	1	432.00	432.00
FRT SHOCK ABSORBER ?	1	65.10	65.10
LH FOG LAMP SUPPORT ?	1	79.10	79.10
RH FOG LAMP SUPPORT ?	1	79.10	79.10
COVER LOWER PART CENTRE ?	1	46.05	46.05
RH PARTIALLY OPEN GRID (SPORT/LUXUR ✓ cut	1	91.00	91.00
RH TRIM SPORT LINE ✓ cut	1	127.40	127.40
FINISHER ROD CENTRE (SPORT LINE) ?	1	55.75	55.75
INSERT AIR INLET MIDDLE (LINES) ?	1	151.70	151.70
FRT BUMPER PANEL PRIMED (LINES) X repair	1	1,084.65	1,084.65
FRT BUMPER LOWER MOUNT ?	1	139.15	139.15
RH HEADLIGHT LED TECHNOLOGY ✓ cut	1	2,808.05	2,808.05
Total Parts :			5,159.05

OD PAPER SURVEY DATE: 22/05/2023
 WITHOUT PREJUDICE
 THINH NGUYEN - TEL/WHATSAPP: (+84) 909 232 062
 CLAIM NO: AVS23/1588
 OFFICER: MS POH KHIM
 EXCESS: TBA
 WORKING DAYS: 3 DAYS
 ** REQUIRED MILEAGE PHOTO, CHASSIS NUMBER PHOTO, CHECK ITEMS APPROVAL BEFORE PROCEED AND BEFORE PAINT PHOTO**
 FINALIZATION WILL SUBJECT TO PART PRICE AND PHOTO PROVIDED