



## Final Report

Estimate No. : **b1 66050**  
 Date Estimated : **19/05/2023**  
 Prepared By : **Jack Ng Guo Ming**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Lam Kee Siong Terence**  
**11 Jalan Mutiara**  
**#06-01**

**Singapore 249191**

**- ACCOUNT - 85**

**Liberty Insurance Pte Ltd**  
**51 Club Street**  
**#03-00 Liberty House**  
**Singapore 069428**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKH8811B	WBA4H32080BH12043	31/10/2017	420iA GC	64193

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include carrying out necessary repairs caused by the accident ✓	850.00		850.00
To respray front bumper ✓	1,038.00		1,038.00
To replace RH high intensity headlight include functionality programming and conducting checks for proper function ✓	481.00		481.00
To check electrical wiring system at the front section for proper function ✓	177.00		177.00
Sundries ✓	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTING PDC/PMA SENSOR FRT ✓ nec	81.35	1.00	0.00	81.35
RH PARTIALLY OPEN GRID (SPORT/LUXURY) ✓	91.00	1.00	0.00	91.00
RH TRIM SPORT LINE ✓	127.40	1.00	0.00	127.40
FRT BUMPER PANEL PRIMED (LINES) ✓ cut & deformed	1,084.65	1.00	0.00	1,084.65
# PLAQUE 82MM ✓ nec	72.85	1.00	0.00	72.85
RH HEADLIGHT LED TECHNOLOGY ✓	2,808.05	1.00	0.00	2,808.05
# (DG/SL) ADHESIVE SET K6 ✓ nec	53.05	1.00	0.00	53.05

# SUPPLEMENTARY ITEMS

Total Labour :	2,626.00 ✓
Total Parts :	4,318.35 ✓
Total Labour & Parts (before GST) :	6,944.35 ✓
Deduction for Excess :	900.00
Total Repair Costs less Excess:	6,044.35
GST @8%:	483.55
<b>Grand Total :</b>	<b>6,527.90</b>

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
 Co Reg No. 197401559W



# Performance Motors

BMW Dealer



## Supplementary

Estimate No. : **b1 66050**  
Date Estimated : **19/05/2023**  
Prepared By : **Jack Ng Guo Ming**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Lam Kee Siong Terence**  
**11 Jalan Mutiara**  
**#06-01**

**Singapore 249191**

**- ACCOUNT - 85**

**Liberty Insurance Pte Ltd**  
**51 Club Street**  
**#03-00 Liberty House**  
**Singapore 069428**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKH8811B	WBA4H32080BH12043	31/10/2017	420iA GC	64193

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTING PDC/PMA SENSOR FRT	81.35	1.00	0.00	81.35
# PLAQUE 82MM	72.85	1.00	0.00	72.85
# (DG/SL) ADHESIVE SET K6	53.05	1.00	0.00	53.05

# SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	207.25
Total Labour & Parts (before GST) :	207.25

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W







