

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23006824/UNY3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC00950		
Claimant Vehicle No :	SHA1073H	Insured Vehicle No :	SLK2102B		
Date of Loss:	04/07/2023	Nature of Claim:	TP	Claim No:	M2303865

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1073H		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU297716
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164283
Colour:	Blue	Odometer:	499675 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,437.08	2,437.08	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,970.00	1,380.00	590.00	29.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,418.08	3,828.08	590.00	13.35
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	4,418.08	3,050.00	1,368.08	30.97
+ GST 8.00/8.00% (S\$)	353.45	244.00	109.45	30.97
Nett Amount (S\$)	4,771.53	3,294.00	1,477.53	30.97

INSPECTION

Date of Assignment:	05/07/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/07/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1073H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Badly Dented	588.80 FL	*588.80 FL
2	1		*FRT FENDER EMBLEM RH	Necessary	26.60 FL	*26.60 FL
3	1		*FRT DOOR ASSY RH	Badly Dented	1,797.20 FL	*1,797.20 FL
4	1		*ROCKER PANEL GARNISH RH	Deformed / Torn	290.00 FL	*290.00 FL
5	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 F	*75.00 F
6	1		*ADVERTISEMENT LOGO - FENDER	Necessary	100.00 F	*100.00 F
7	1		*ADVERTISEMENT LOGO - DOOR	Necessary	100.00 F	*100.00 F
					Sub Total (S\$)	2,977.60 2,977.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	540.52 540.52
					Total Parts (S\$)	2,437.08 2,437.08

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAYPAINT	New	800.00	700.00
3	TUFF KOTE	New	50.00	30.00
4	TRANSFER DOOR PARTS	New	120.00	50.00
Gross Labour Cost (\$\$)			1,970.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >