

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**India International Insurance Pte Ltd  
6 Raffles Quay, #22-00  
Singapore 048580**Our File No:** CS/III23006825/KVY3E2**Date:** 20/07/2023**REFERENCE**

Insured/Claimant:	CHONG SENGIE	Policy No:	D23MPCM000506		
Date of Loss:	05/07/2023	Nature of Claim:	OD	Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLZ2449Y</b>	Engine No:	CHZ644929
Make & Model:	VOLKSWAGEN GOLF, 999cc TSI (A)	Chassis No:	WVWZZZAUZJW155179
Reg. Date:	26/04/2018 (Man. Year: 2017)	Odometer:	51797 km
Colour:	Metalic Light Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>5,350.00</b>		
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	-600.00	4,750.00	-5,350.00	891.67
<b>+ GST 8.00/8.00% (S\$)</b>	0.00	380.00	-380.00	
<b>Nett Amount (S\$)</b>	<b>-600.00</b>	<b>5,130.00</b>	<b>-5,730.00</b>	<b>955.00</b>

**INSPECTION**

Date of Assignment: 06/07/2023

Date Inspected: 06/07/2023 Inspected At:

Optima Werkz Pte Ltd (HQ)  
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK  
Autopoint  
Singapore 568047

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
<b>Parts:</b> 144	VOLKSWAGEN GOLF 999cc TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ2449Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**