

Date : 05/07/2023
 Vehicle No: SLZ2449Y
 Model: VOLKSWAGEN GOLF TSI
 Chassis: WVWZZZAUZJW155179-2017
 Reg. Year: 2018
 Policy No: D23MPCM000506
 Date of Accident: 05/07/2023
 Estimator: TING AN

TO MOTOR CLAIM DEPT
 INDIA INT. INSURANCE PTE LTD
 6 RAFFLES QUAY
 #22-00 SINGAPORE 048580

Not Notched
11 Pm @ 5350h
Permy After Paint
Ex TBA 5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		<i>Bu</i> \$900.00 ✓
2	FRONT BONNET HINGE LH	1		<i>DIY</i> \$70.00 ✓
3	FRONT BONNET HINGE RH	1		<i>DIY</i> \$70.00 ✓
4	FRONT BONNET STRUT LH	1		<i>Pa</i> \$80.00 X
5	FRONT BONNET STRUT RH	1		<i>Pa</i> \$80.00 X
6	FRONT BONNET LOCK	1		<i>DIY</i> \$145.00 ✓
7	FRONT BONNET INSULATOR	1		<i>Pa</i> \$215.00 X
8	FRONT GRILLE ASSY	1		<i>CM</i> \$280.00 ✓
9	FRONT GRILLE EMBLEM	1		<i>CM</i> \$75.00 ✓
10	FRONT AIR DUCT	1		<i>DIY</i> \$45.00 ✓
11	FRONT AIR DUCT TOP COVER	1		<i>CM</i> \$30.00 ✓
12	FRONT HEADLAMP LH	1		<i>CM</i> \$410.00 ✓
13	FRONT HEADLAMP RH	1		<i>Pa</i> \$410.00 ✓
14	FRONT HEADLAMP UPPER PANEL LH	1		<i>Bu</i> \$45.00 ✓
15	FRONT HEADLAMP UPPER PANEL RH	1		<i>Bu</i> \$45.00 ✓
16	FRONT BUMPER	1		<i>Bu</i> \$680.00 ✓
17	FRONT BUMPER SIDE BRACKET LH	1		<i>DIY</i> \$40.00 ✓
18	FRONT BUMPER SIDE BRACKET RH	1		<i>Pa</i> \$40.00 X
19	FRONT BUMPER LOWER GRILLE	1		<i>DIY</i> \$145.00 ✓
20	FRONT BUMPER SIDE GRILLE LH	1		<i>DIY</i> \$50.00 ✓
21	FRONT BUMPER REINFORCEMENT	1		<i>Pa</i> \$410.00 ✓
22	FRONT BUMPER ABSORBER FOAM	1		<i>CM</i> \$65.00 ✓
23	FRONT SUPPORT PANEL	1		<i>CM</i> \$580.00 ✓
24	FRONT SUPPORT BRACE PANEL	1		<i>DIY</i> \$45.00 ✓
25	FRONT A-PILLAR MOULDING LH	1		<i>DIY</i> \$40.00 ✓
26	FRONT FENDER LH	1		REPAIR
27	FRONT FENDER RH	1		REPAIR
SUB TOTAL				\$4,995.00
COST +10%				\$499.50
PARTS TOTAL				\$5,494.50

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 05/07/2023
 Vehicle No: SLZ2449Y
 Model: VOLKSWAGEN GOLF TSI
 Chassis: WVVZZZAUZJW155179-2017
 Reg.Year: 2018
 Policy No: D23MPCM000506
 Date of Accident: 05/07/2023

TO MOTOR CLAIM DEPT
 INDIA INT. INSURANCE PTE LTD
 6 RAFFLES QUAY
 #22-00 SINGAPORE 048580

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>nn</i> \$40.00
2	FRONT BUMPER CLIPS	1		<i>nc</i> \$50.00
3	FRONT NUMBER PLATE & HOLDER	1		<i>R1</i> \$50.00
S/N TOTAL				\$140.00

X
 ✓
 4550

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

600
 \$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

Pool
 \$1,000.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 *200*

LABOUR TOTAL \$2,220.00

TING AN TOTAL \$7,854.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Branch (Motor Insurance Claims)
 Signature: _____
 Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Date : 11/07/2023 TO MOTOR CLAIM DEPT
 Vehicle No: SLZ2449Y INDIA INT. INSURANCE PTE LTD
 Model: VOLKSWAGEN GOLF TSI 6 RAFFLES QUAY
 Chassis: WVWZZZAUZJW155179-2017 #22-00 SINGAPORE 048580
 Reg.Year: 2018
 Policy No: D23MPCM000506
 Date of Accident: 05/07/2023

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT AIR DEFLECTOR LH	1		CM \$30.00
2	FRONT AIR DEFLECTOR RH	1		CM \$30.00
3	FRONT BUMPER CENTER BRACKET	1		D/I \$70.00
SUB TOTAL				\$130.00
COST +10%				\$13.00
PARTS TOTAL				\$143.00

TING AN TOTAL \$143.00

Finalize:

Parts: \$5038

Supp: \$143

Nett: \$95

Labour: \$1420

↓/s : \$6696 less 20% - \$5356.80

↓
\$5350

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1393

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 563047
Tel: (+65) 6481 1822 | Fax: (+65) 6481 1011

