

Date : 05/07/2023
Vehicle No: SLZ2449Y
Model: VOLKSWAGEN GOLF TSI
Chassis: WVVZZZAUZJW155179-2017
Reg.Year: 2018
Policy No: D23MPCM000506
Date of Accident: 05/07/2023
Estimator: TING AN

TO MOTOR CLAIM DEPT
INDIA INT. INSURANCE PTE LTD
6 RAFFLES QUAY
#22-00 SINGAPORE 048580

Not Attached
L1 Pm @
Permy After Paint
Ex TBA 5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		<i>Bu</i> \$900.00	✓
2	FRONT BONNET HINGE LH	1		<i>Diy</i> \$70.00	✓
3	FRONT BONNET HINGE RH	1		\$70.00	?
4	FRONT BONNET STRUT LH	1		<i>Bu</i> \$80.00	X
5	FRONT BONNET STRUT RH	1		<i>Ju</i> \$80.00	X
6	FRONT BONNET LOCK	1		\$145.00	?
7	FRONT BONNET INSULATOR	1		<i>Bu</i> \$215.00	X
8	FRONT GRILLE ASSY	1		<i>CRA</i> \$280.00	—
9	FRONT GRILLE EMBLEM	1		<i>CM</i> \$75.00	—
10	FRONT AIR DUCT	1		\$45.00	?
11	FRONT AIR DUCT TOP COVER	1		<i>CM</i> \$30.00	✓
12	FRONT HEADLAMP LH	1		<i>CM</i> \$410.00	✓
13	FRONT HEADLAMP RH	1		\$410.00	?
14	FRONT HEADLAMP UPPER PANEL LH	1		<i>Bu</i> \$45.00	—
15	FRONT HEADLAMP UPPER PANEL RH	1		<i>Bu</i> \$45.00	—
16	FRONT BUMPER	1		<i>Bu</i> \$680.00	—
17	FRONT BUMPER SIDE BRACKET LH	1		<i>Diy</i> \$40.00	—
18	FRONT BUMPER SIDE BRACKET RH	1		<i>Bu</i> \$40.00	X
19	FRONT BUMPER LOWER GRILLE	1		<i>Net</i> \$145.00	✓
20	FRONT BUMPER SIDE GRILLE LH	1		<i>Net</i> \$50.00	—
21	FRONT BUMPER REINFORCEMENT	1		\$410.00	?
22	FRONT BUMPER ABSORBER FOAM	1		\$65.00	?
23	FRONT SUPPORT PANEL	1		\$580.00	?
24	FRONT SUPPORT BRACE PANEL	1		\$45.00	?
25	FRONT A-PILLAR MOULDING LH	1		<i>Diy</i> \$40.00	✓
26	FRONT FENDER LH	1		REPAIR	
27	FRONT FENDER RH	1		REPAIR	
SUB TOTAL				\$4,995.00	
COST +10%				\$499.50	
PARTS TOTAL				\$5,494.50	

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 05/07/2023
 Vehicle No: SLZ2449Y
 Model: VOLKSWAGEN GOLF TSI
 Chassis: WVVZZZAUZJW155179-2017
 Reg.Year: 2018
 Policy No: D23MPCM000506
 Date of Accident: 05/07/2023

TO MOTOR CLAIM DEPT
 INDIA INT. INSURANCE PTE LTD
 6 RAFFLES QUAY
 #22-00 SINGAPORE 048580

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>nn</i> \$40.00
2	FRONT BUMPER CLIPS	1		<i>mc</i> \$50.00
3	FRONT NUMBER PLATE & HOLDER	1		<i>pt</i> \$50.00
S/N TOTAL				\$140.00

X
✓
45%

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

600
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

\$1,000.00 *pool*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120.00 *?*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 *202*

LABOUR TOTAL \$2,220.00

TOTAL \$7,854.50

TING AN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Branch (Motor Insurance Claims)

Signature: _____
 Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993