

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 03/07/2023
TP Veh Reg No: SNH588M

Estimate No: EST2300256
Date: 06 Jul 2023

Veh Reg No: SMQ9205Z
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3601182182
Reg. Date: 10/12/2019
Your Ref No: SNH588M

Estimate Repair Cost to Vehicle No :SMQ9205Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BUMPER	660.90	
2	1 PC REAR BUMPER REINFORCEMENT	360.10	
3	1 PC REAR BUMPER SIDE RETAINER LH	167.90	
4	1 PC REAR BUMPER RETAINER (SMALL) LH	65.00	
5	1 PC REAR BUMPER REFLECTOR - LH	198.70	
6	1 PC REAR BUMPER MUDFLAP LH	99.20	
7	1 PC BOOT LID	852.90	
8	1 PC BOOTLID LOGO	66.90	
9	1 PC BOOT LID "VIOS" EMBLEM	49.40	
10	1 PC BOOTLID "5" EMBLEM	43.60	
11	1 PC BOOT LID LOCK	432.50	
12	1 PC BOOT LID LOCK CHECKER	39.80	
13	1 PC BOOT LID RUBBER	190.10	
14	1 PC BOOT LID LAMP LH	446.90	
15	1 PC BOOTLID TRIM	352.00	
16	1 PC REAR PANEL	863.20	
17	1 PC REAR PANEL TRIM	301.50	
18	1 PC TAIL LAMP LH	687.90	
19	1 PC TAIL LAMP LH PANEL	128.20	
20	1 PC REAR FENDER LH	980.80	
21	1 PC REAR FENDER TRIM LH	356.40	
22	1 PC REAR FENDER INNER PANEL LH	348.30	
23	1 PC REAR FENDER AIR VENT COVER	67.60	
24	1 PC SPARE TYRE PANEL	755.10	
25	1 PC REAR SPARE TYRE PANEL LH SIDE PANEL	151.70	
26	1 PC SPARE TYRE PANEL LH SPONGE	329.60	
27	1 PC REAR DOOR LH	1,013.40	
28	1 PC REAR DOOR LOCK LH	655.30	
29	2 PCS REAR DOOR HINGE LH	211.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 03/07/2023
TP Veh Reg No: SNH588M

Estimate No: EST2300256

Date: 06 Jul 2023

Veh Reg No: **SMQ9205Z**

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601182182

Reg. Date: 10/12/2019

Your Ref No: SNH588M

Estimate Repair Cost to Vehicle No :SMQ9205Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR DOOR CHECK LH	218.90	
31	1 PC REAR DOOR OUTER HANDLE LH	259.80	
32	1 PC REAR DOOR OUTER HANDLE COVER LH	65.60	
33	1 PC REAR LH DOOR OUTER MOULDING	166.70	
34	1 PC REAR DOOR GLASS CHANNEL LH	108.70	
35	1 PC REAR LH DOOR FRAME BLACK TAPE	110.50	
36	1 PC REAR DOOR GLASS REGULATOR LH	244.10	
37	1 PC REAR DOOR GLASS REGULATOR ASSY LH	765.50	
38	1 PC REAR DOOR RUBBER LH	193.90	
39	1 PC REAR DOOR TRIM LH	805.10	
40	1 PC FRT DOOR LH	1,183.30	
41	1 PC FRT LH DOOR LOCK	655.30	
42	2 PCS FRT DOOR HINGE LH	211.00	
43	1 PC FRT DOOR CHECK LH	218.90	
44	1 PC FRT DOOR OUTER MOULDING LH	181.70	
45	1 PC FRT DOOR OUTER HANDLE LH	478.70	
46	1 PC FRT DOOR OUTER HANDLE LH COVER	65.60	
47	1 PC FRT DOOR SIDE MIRROR LH	1,360.50	
48	1 PC FRT DOOR SIDE MIRROR COVER LH	118.70	
49	1 PC FRT DOOR RUBBER LH	221.40	
50	1 PC FRT DOOR GLASS REGULATOR LH	299.00	
51	1 PC FRT DOOR GLASS REGULATOR MOTOR LH	765.50	
52	1 PC FRT DOOR GLASS CHANNEL LH	165.70	
53	1 PC FRT DOOR BLACK TAPE LH	128.50	
54	1 PC FRT DOOR TRIM LH	942.30	
55	1 PC FRT LH ROKER PANEL	672.60	
56	1 PC FRT FENDER LH	827.50	
57	1 PC FRT FENDER COWLING LH	222.80	
58	1 PC FRT FENDER LH FOG LAMP COVER	123.90	
59	1 PC FRT FENDER FOG LAMP LH	308.60	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 03/07/2023
TP Veh Reg No: SNH588M

Estimate No: EST2300256

Date: 06 Jul 2023

Veh Reg No: **SMQ9205Z**

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601182182

Reg. Date: 10/12/2019

Your Ref No: SNH588M

Estimate Repair Cost to Vehicle No :SMQ9205Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
60	1 PC HEADLAMP LH	1,393.40	
61	1 PC FRT BUMPER	583.90	
62	1 PC FRT BUMPER SIDE RETAINER LH	108.70	
63	1 PC REAR AXLE	3,116.40	
64	1 PC REAR SHOCK ABSORBER LH	147.40	
65	1 PC REAR WHEEL HUB WITH BEARING LH	917.10	
66	1 PC FRT KNUCKLE ARM LH	717.30	
67	1 PC FRT LOWER ARM LH	1,321.50	
68	1 PC FRT SHOCK ABSORBER LH	453.60	
69	1 PC FRT WHEEL HUB WITH BEARING LH	644.20	
70	1 PC STEERING RACK & PINION	3,115.80	
		35,485.50	
		Less 25%	8,871.38
			26,614.33
	Special Net		
71	1 SET REAR BUMPER CLIPS	40.00	
72	2 PCS "L" PLATE BRACKET	70.00	
73	1 PC BOOT LID NUMBER '680' STICKER	35.00	
74	1 SET BOOTLID TRIM CLIPS	60.00	
75	1 SET REAR PANEL TRIM CLIPS	40.00	
76	1 SET REAR FENDER TRIM CLIPS LH	60.00	
77	1 PC REAR WINDSCREEN SEAL	60.00	
78	1 PC REAR WINDSCREEN SEALANT	60.00	
79	1 SET REAR DOOR LH TRIM CLIPS	60.00	
80	1 SET FRT DOOR LH TRIM CLIPS	60.00	
81	1 SET FRT FENDER COWLING CLIPS LH	60.00	
82	1 PC FRT FENDER NUMBER '680' STICKER	35.00	
83	1 SET FRT BUMPER CLIPS	40.00	
84	1 SET FRT BUMPER GRILLE CLIPS	40.00	
85	1 PC REAR SPORTS RIM LH	800.00	
86	1 PC REAR TYRE LH	320.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 03/07/2023
TP Veh Reg No: SNH588M

Estimate No: EST2300256

Date: 06 Jul 2023

Veh Reg No: **SMQ9205Z**

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601182182

Reg. Date: 10/12/2019

Your Ref No: SNH588M

Estimate Repair Cost to Vehicle No :SMQ9205Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
87	1 PC FRT SPORTS RIM LH	800.00	
88	1 PC FRT TYRE LH	320.00	
		2,960.00	2,960.00
	Labour		
89	1 TO CHECK WIRING	50.00	
90	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
91	1 TO REMOVE AND REFIT REAR SEAT CUSHION	200.00	
92	1 TO REMOVE AND REFIT PETROL TANK	200.00	
93	1 TO REMOVE AND REFIX REAR DOOR GLASS	120.00	
94	1 TO REMOVE AND REFIX FRT DOOR GLASS	120.00	
95	1 TO REMOVE AND REFIT INNER TRIM	150.00	
96	1 TO REMOVE AND REFIT DOOR INNER TRIM	200.00	
97	1 TO REMOVE AND REFIT UNDERCARRIAGE	680.00	
98	1 TO CHECK WHEEL ALIGNMENT	120.00	
99	1 TO SPRAY PANEL SEALANT	150.00	
100	1 TO SPRAY PAINTING	2,300.00	
101	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,500.00	
102	1 TO REMOVE AND REFIT FRT UNDERCARRIAGE	480.00	
		7,390.00	7,390.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 03/07/2023
TP Veh Reg No: SNH588M

Estimate No: EST2300256

Date: 06 Jul 2023

Veh Reg No: **SMQ9205Z**

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601182182

Reg. Date: 10/12/2019

Your Ref No: SNH588M

Estimate Repair Cost to Vehicle No :SMQ9205Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 36,964.33
		Add GST @ 8%	2,957.15
		Total Amount Payable	<u>S\$ 39,921.48</u>

TOTAL: SINGAPORE DOLLAR THIRTY NINE THOUSAND NINE HUNDRED TWENTY ONE AND CENTS FORTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE