

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III23006839/KVY3E2**Date:** 24/07/2023**REFERENCE**

Insured/Claimant:	933 MOTORING	Policy No:	D22MFL0002743		
Date of Loss:	05/07/2023	Nature of Claim:	OD	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2704U	Engine No:	2ZR8449827
Make & Model:	TOYOTA C-HR, 1.8 (A)	Chassis No:	ZYX102122641
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	119904 km
Colour:	Metallic Red		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Habilead 9 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Habilead 9 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		9,800.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	-1,500.00	8,300.00	-9,800.00	653.33
+ GST 8.00/8.00% (S\$)	0.00	664.00	-664.00	
Nett Amount (S\$)	-1,500.00	8,964.00	-10,464.00	697.60

INSPECTION

Date of Assignment:	06/07/2023	
Date Inspected:	07/07/2023 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat #05-67/68, Carros Centre Singapore 737869
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2023)
Parts: M1-SUV	TOYOTA C-HR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMC2704U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >