



TECH CHOON

AUTOMOTIVE PRIVATE LIMITED

Address: 60 Jalan Lam Huat #05-45, Carros Centre, Singapore 737869
Office: 6367 0710 Fax: 6368 8025 E-mail: tcawtl@singnet.com.sg

NOT Authorised

Repair After Paint 6/1 Day &

24 days

LONPAC INSURANCE BHD
300, BEACH ROAD, #17-04/06
THE CONCOURSE
SINGAPORE 199555
ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPAIR BILL

YOUR REF : GBC4141K
TYPE OF CLAIM : THIRD PARTY CLAIMS
CLAIMANT : CHIA KOK HENG
VEHICLE NO. : SMU2968E
MAKE/ MODEL : HONDA VEZEL
ACCIDENT DATE : 27/6/2023

MATERIAL COST

1	1PC	FRONT WINDSCREEN
2	1PC	FRONT WINDSCREEN MOULDING
3	1PC	LH FRONT WIPER ARM
4	1PC	LH FRONT WIPER BLADE
5	1PC	FRONT BUMPER COVER
6	2 PCS	FRONT BUMPER RETAINERS
7	6 PCS	FRONT BUMPER CLIPS
8	1PC	FRONT BUMPER PDC SENSOR
9	1PC	FRONT BUMPER PDC SENSOR HOLDERS
10	1PC	FRONT BUMPER PDC SENSOR WIRE HARNESS
11	1PC	LH FOG LAMP
12	1PC	LH FOG LAMP BEZEL
13	1PC	FOG LAMP HOLDER INNER
14	1PC	FRONT BUMPER LOWER GRILLE
15	1PC	FRONT BUMPER LOWER PAD
16	1PC	FRONT BUMPER REINFORCEMENT
17	1PC	FRONT BUMPER REINFORCEMENT TOP TRIM LH
18	1PC	FRONT BUMPER REINFORCEMENT TOP TRIM RH
19	3 PCS	FRONT BUMPER REINFORCEMENT TOP TRIM CLIPS
20	1PC	FRONT AMBIENT SENSOR
21	2 PCS	HEADLAMPS
22	1PC	HEADLAMP CHROME LH
23	1PC	HEADLAMP CHROME RH
24	2 PCS	HEADLAMPS LOWER BRACKET
25	1PC	LH FRONT FENDER
26	1PC	RH FRONT FENDER
27	1PC	LH FRONT FENDER DUST COVER
28	12 PCS	FRONT FENDER DUST COVER CLIPS
29	2 PCS	FRONT FENDER HYBRID EMBLEM
30	1PC	FRONT GRILLE
31	1PC	FRONT GRILLE CHROME
32	1PC	FRONT GRILLE MID
33	1PC	FRONT GRILLE LOGO
34	1PC	FRONT LOGO BASE
35	2 PCS	FRONT GRILLE SIDE INNER BRACKET
36	1PC	BONNET
37	1PC	BONNET RUBBER SEALS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CM 2,514.25 ✓

RM 146.75 ✓

\$ 141.75 ✓

\$ 68.88 ✓

RM 626.63 ✓

CM 48.75 ✓

RM 44.18 ✓

\$ 250.00 ✓

\$ 100.00 ✓

\$ 137.50 ✓

\$ 381.75 ✓

\$ 41.75 ✓

\$ 68.88 ✓

Dr 433.88 ✓

Dr 134.25 ✓

RM 475.50 ✓

Dr 30.13 ✓

Dr 30.13 ✓

RM 22.09 ✓

\$ 369.75 ✓

Dr 5,028.50 ✓

\$ 150.13 ✓

\$ 150.13 ✓

RM 87.75 ✓

RM 479.25 ✓

RM 479.25 ✓

RM 146.75 ✓

RM 88.35 ✓

RM 137.75 ✓

RM 475.50 ✓

RM 266.00 ✓

RM 266.00 ✓

RM 37.63 ✓

RM 251.63 ✓

RM 98.25 ✓

RM 639.25 ✓

RM 31.38 ✓

38	1PC	BONNET INSULATOR	\$	CM	152.88	—
39	12 PCS	BONNET INSULATOR CLIPS	\$	M	88.35	—
40	2 PCS	BONNET HINGES	\$	M	100.25	—
41	1PC	BONNET LOCK	\$	Di	122.63	—
42	1PC	BONNET LOCK BRACKET	\$	CM	138.00	—
43	3 PCS	BONNET LOCK BRACKER CLIPS	\$	M	22.09	—
44	1PC	FRONT SUPPORT PANEL	\$	M	802.13	—
45	1PC	FRONT SUPPORT PANEL TOP COVER	\$	M	75.13	—
46	10 PCS	FRONT SUPPORT PANEL TOP COVER CLIPS	\$	M	73.63	—
47	1PC	FRONT SUPPORT PANEL LOWER	\$		611.38	?
48	1PC	FRONT AIR INTAKE DUCT	\$	M	76.38	—
49	2 PCS	FRONT AIR INTAKE DUCT CLIPS	\$	M	14.73	—
50	1PC	FRONT AIR INTAKE HOSE	\$		63.88	?
51	1PC	AIR INTAKE LOWER DUCTING	\$		376.00	?
52	1PC	AIR RESONATOR	\$		225.13	?
53	1PC	INTAKE MANIFOLD	\$		507.63	?
54	1PC	INTAKEMANIFOLD VACUUM HOSE	\$		39.25	?
55	1PC	BATTERY POSITIVE TERMINAL	\$		251.75	?
56	1PC	AIR-CON CONDENSER	\$	M	710.13	✓
57	1PC	AIR-CON CONDSEF FAN COWLING	\$		123.25	?
58	1PC	AIR-CON CONDENSER FAN BLADE	\$		82.63	?
59	1PC	AIR-CON CONDENSER FAN MOTOR	\$		314.25	?
60	1PC	RADIATOR ASSY	\$		1,235.13	?
61	1PC	RADIATOR FAN COWLING	\$		123.25	?
62	1PC	RADIATOR FAN BLADE	\$		82.63	?
63	1PC	RADIATOR FAN MOTOR	\$		314.25	?
64	1PC	RADIATOR TOP HOSE	\$		44.13	?
65	1PC	REAR BUMPER	\$	M	714.25	—
66	1PC	REAR BUMPER LH REFLECTOR	\$	CM	185.13	—
67	1PC	REAR BUMPER RH REFLECTOR	\$	185.13	185.13	?
68	2 PCS	REAR BUMPER NUT	\$	M	15.00	—
69	1PC	REAR BUMPER LH SIDE PAD	\$	M	150.13	—
70	1PC	REAR BUMPER RH SIDE PAD	\$		150.13	?
71	1PC	REAR BUMPER CLIPS	\$	M	58.90	—
72	1PC	REAR UNDER LOWER GARNISH	\$	CM	238.00	—
73	1PC	RH REAR FENDER	\$	M	1,264.25	—
74	1PC	LH REAR FENDER	\$	M	1,264.25	—
75	1PC	LH REAR FENDER DUST COVER	\$	Not in	277.25	—
76	1PC	LH REAR FENDER ARCH TRIM	\$	M	146.38	—
77	1PC	RH FENDER REAR DUST COVER	\$	M	277.25	—
78	8 PCS	RH FENDER REAR DUST COVER CLIP	\$	M	60.00	X
79	8 PCS	LH FENDER REAR DUST COVER CLIP	\$	M	60.00	X
80	1PC	RH REAR FENDER ARCH TRIM	\$	M	146.38	X
81	1PC	RH REAR FENDER AIR POCKET	\$	M	225.38	X
82	1PC	LH TAIL LAMP	\$	M	536.38	—
83	2 PCS	TAIL LAMP HOLDER	\$	M	20.00	—
84	1PC	RH TAIL LAMP	\$	M	536.38	—
85	1PC	REAR WINDSCREEN	\$	Shatter	1,067.00	—
86	2 PCS	REAR WINDSCREEN MOULDING	\$	M	375.75	—
87	1PC	TAIL GATE ASSY	\$	M	1,139.25	—
88	2 PCS	TAIL GATE ABSORBER	\$		662.75	?
89	1PC	REAR BUMPER RETAINER LH	\$	CM	68.88	—
90	1PC	REAR BUMPER RETAINER RH	\$	CM	68.88	—
91	1PC	TAIL GATE VEZEL EMBLEM	\$	M	63.00	—
92	1PC	TAIL GATE HYBRID EMBLEM	\$	M	64.25	—
93	1PC	TAIL GATE SPOILER	\$		639.25	?
94	1PC	TAILGATE RH REFLECTOR	\$	M	561.38	—
95	1PC	TAILGATE LH REFLECTOR	\$	CM	555.13	—
96	1PC	TAILGATE OUTER GARNISH	\$	M	294.25	—
97	6 PCS	TAILGATE OUTER GARNISH CLIP	\$	M	45.00	—
98	1PC	TAILGATE OUTER GARNISH "H" LOGO	\$	M	31.63	—
99	1PC	TAILGATE INNER LOCK	\$	M	146.75	—
100	1PC	TAILGATE INNER LOCK STRIKER CABLE	\$	M	276.00	—

101	IPC	TAILGATE INNER PULL PULL POCKET COVER
102	IPC	TAILGATE INNER TRIM BOARD MAIN
103	IPC	TAILGATE INNER TRIM BOARD LH
104	IPC	TAILGATE INNER TRIM BOARD RH
105	IPC	TAILGATE INNER TRIM BOARD UPPER
106	2 PCS	TAILGATE HINGES
107	IPC	TAILGATE W/STRIP
108	2 PCS	REAR NUMBER PLATE LAMP
109	IPC	REAR WIPER BLADE
110	IPC	REAR WIPER ARM
111	IPC	REAR WIPER ARM COVER
112	IPC	REAR WIPER MOTOR
113	IPC	REAR ANTENNA
114	IPC	HYBRID BATTERY PACK
115	IPC	HYBRID BATTERY CASING TOP
116	IPC	HYBRID BATTERY CASING LOWER
117	IPC	HYBRID BATTERY AIR DUCT
118	IPC	REAR END PANEL P-?
119	IPC	REAR END PANEL INNER TRIM
120	3 PCS	REAR END PANEL INNER TRIM CLIPS
121	IPC	REAR FLOOR PANEL
122	IPC	REAR FLOOR TOOL TRAY
123	IPC	REAR END PANEL INNER TRIM - LH
124	IPC	REAR FENDER INNER TRIM LH UPPER
125	IPC	REAR FENDER INNER TRIM RH UPPER
126	IPC	REAR FENDER INNER TRIM RH
127	16 PCS	REAR FENDER INNER TRIM CLIPS
128	IPC	REAR EXHAUST MUFFLER
129	IPC	REAR EXHAUST MUFFLER HEAT SHEILD
130	2 PCS	REAR EXHAUST MUFFLER MOUNTING
131	IPC	MID EXHAUST PIPE
132	2 PCS	MID EXHAUST PIPE MOUNTING
133	IPC	REAR LH TIRE
134	IPC	REAR RH TIRE
135	2 PCS	RR SHOCK ABSORBER
136	2 PCS	RR SHOCK ABSORBER TOP MOUNTING

LESS : DISCOUNT 20%

\$	150.50	?
\$	238.00	✓
\$	68.88	✓
\$	68.88	?
\$	154.25	?
\$	165.25	✓
\$	147.00	✓
\$	115.75	✓
\$	72.88	✓
\$	82.63	✓
\$	47.63	✓
\$	256.75	✓
\$		
\$	11,809.88	?
\$	361.13	?
\$	252.25	?
\$		
\$	1,096.38	✓
\$	146.75	✓
\$	22.09	✓
\$	983.88	?
\$	573.88	?
\$	400.13	✓
\$	360.88	?
\$	360.88	X
\$	400.13	?
\$	117.80	?
\$	724.25	?
\$	58.88	?
\$	75.25	?
\$	874.13	?
\$	75.25	?
\$	350.00	908in
\$	350.00	X
\$	1,444.00	X
\$	805.25	X
\$		
\$	11,819.64	
\$	47,278.55	

S/Nett Items

1	1 PC	FRONT WINDSCREEN SEALANT
2	1 PC	FRONT WINDSCREEN INNER SEAL
3	1 PC	"U" BRACKET
4	1 PC	FRONT NUMBER PLATE
5	1 BTL	RADIATOR COOLANT
6	1 PC	REAR BUMPER PLATE
7	1 PC	REAR W/ SCREEN SEALANT
8	1 PC	REAR W/ INNER SCREEN SEALANT
9	1 SET	REVERSE SENSOR
10	2 SET	REVERSE CAMERA
11	3 SET	REAR CAMERA

\$	40.00	✓
\$	20.00	✓
\$	28.00	✓
\$	35.00	✓
\$	40.00	✓
\$	35.00	✓
\$	40.00	✓
\$	20.00	✓
\$	220.00	2005in
\$	700.00	?
\$	600.00	?
\$	1,778.00	

LABOUR CHARGE :

FRONT

1	TO REPLACE FRONT WINDSCREEN
2	RI AIR-CON AND RECHARGE GAS
3	TO REPLACE AIR INTAKE MANIFOLD
4	TO REPLACE BATTERY POSITIVE TERMINAL AND CONDUCT FINAL TESTING

\$	400.00	1200
\$	180.00	1000
\$	100.00	?
\$	120.00	✓

5	TO REMOVE DAMAGED PARTS AND ATTACHMENT, PANEL BEAT AND REPAIR RH FRONT FENDERS, FRT INNER PANEL AND FRT CHASSIS RAIL. CUTTING/ WELDING AND REPLACE FRONT END DAMAGED BODY PARTS.	\$	3,000.00	900-1200/
6	TO SPRAY PAINTING FRT BUMPER, BONNET, BOTH FRONT FENDERS, FRONT INNER PANELS	\$	1,500.00	1000/
REAR				
1	REPLACE REAR WINDSCREEN	\$	250.00	120/
2	RI BOOT INTERIOR TRIM, SEATS, CARPETING ETC.	\$	350.00	100/
3	RI FUEL TANK	\$	400.00	60/
4	RI REAR SUSPENSION AND UNDERCARRIAGE	\$	380.00	200/
5	REMOVE DAMAGED PARTS AND ATTACHMENTS, PANEL BEAT AND REPAIR REAR WHEEL HOUSING PANELS, CHASSIS FRAME, SIDE PANELS, RH REAR FENDER. CUTTING/WELDING AND REPLACE REAR END DAMAGED BODY PARTS.	\$	5,800.00	2400/
6	SPRAY PAINTING- RR BUMPER SIDE PADS, TAILGATE, BOTH REAR FENDERS TAILGATE, REAR END PANEL, REAR FLOOR PANEL AND REAR INNER PANEL	\$	2,500.00	1400/
OTHERS				
1	RECOVER AND TOWING CHARGES	\$	(Bill) 120.00	?
2	ISOLATE AND REMOVE HYBRID BATTERY SUPPLY SYSTEM. REPLACE HYBRID BATTERY PACK AND CONDUCT FINAL TESTING	\$	2,500.00	?
3	TO MOUNT VEHICLE ON BENCH TO CARRY OUT CHASSIS ALIGNMENT REPAIRS	\$	180.00	?
4	RUSTPROOFING	\$	250.00	210/
5	RESET ECU	\$	200.00	?
6	RESET WHEEL ALIGNMENT	\$	150.00	60/
7	SUPPLY AND INSTALL FRONT AND REAR WINDSCREEN SOLAR FILM	\$	450.00	?
			\$	67,886.55
GST 8%:			\$	5,430.92
			\$	<u>73,317.47</u>

TOH AH SWEE SPRAY PAINTING CO.
WEI SI (TEL: 63660286)