

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 33004

Your Reference : MOMVP000003956-03-000

Accident Date : 21-Jun-2023

Date : 23-Jun-2023

Our Ref : 023338 / THERESA

PAGE : 1

GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVE #16-01

CENTENNIAL TOWER

Singapore 039190

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA 1.6 (2015) SKV4908J

=====

1 pc rear bumper		250.00 c
1 pc LH rear bumper side retainer		20.00 c
10 pcs rear bumper clips	@ S\$ 1.80	18.00 c
1 pc LH rear bumper reflector		36.00 c
1 pc LH rear bumper mudflap		38.00 c
1 pc LH rear fender		630.00 c
1 pc LH rear fender inner shield		35.00 c
10 pcs LH rear fender inner shield clips	@ S\$ 1.80	18.00 c
1 pc LH taillamp		190.00 c
1 pc LH taillamp clips		5.00 c
1 pc bootlid logo		30.00 c
1 pc bootlid "ELANTRA" emblem		38.00 c
1 pc bootlid "GLS" emblem		26.00 c
1 pc fuel lid cover		38.00 c
1 pc LH rear door		520.00 c
1 pc LH rear door black sticker-No.1		24.00 c
1 pc LH rear door black sticker-No.2		24.00 c
1 pc LH rear door black sticker-No.3		24.00 c
1 pc LH rear door lock		130.00 c
1 pc LH rear door outer handle		60.00 c
1 pc LH frt door		630.00 c
1 pc LH frt door black sticker No.1		24.00 c
1 pc LH frt door black sticker No.2		24.00 c

Con't Page 2 ...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000003956-03-000
Our Ref : 023338

Page : 2
No. : 33004

1 pc LH frt door outer handle	60.00 c	
1 pc LH frt door outer handle base	150.00 c	
1 pc LH frt door weatherstrip	75.00 c	
1 pc LH wing mirror	230.00 c	
1 pc LH wing mirror cover	100.00 c	
1 pc LH wing mirror signal	70.00 c	
1 pc LH rear wheel bearing	160.00 c	

	3,677.00	
Add 10% :	367.70	

		4,044.70
1 pc rear windscreen glass sealant		40.00 sn
1 pc rear windscreen glass damping seal		20.00 sn
1 pc LH rear rim		580.00 sn
1 pc LH rear tyre		380.00 sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		1,000.00
To focus taillamps. To check rear wiring and lighting operation.		50.00
To remove and refit rear windscreen glass and conduct water leak test		120.00
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works		120.00
To remove door's fittings		200.00
To dismantle and check rear under-carriage. To replace affected portions.		120.00

Con't Page 3 ...

金興(龔)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming AutoCity
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000003956-03-000
Our Ref : 023338

Page : 3
No. : 33004

To conduct rear wheel alignment test.	100.00
To putty and respray on affected portions.	1,400.00
Total :	----- S\$ 8,174.70 =====

Singapore Dollars Eight Thousand One Hundred and Seventy Four and Cents Seventy Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.