

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 33004

Your Reference : MOMVP000003956-03-000

Accident Date : 21-Jun-2023

Date : 23-Jun-2023

Our Ref : 023338 / SANDRA

PAGE : 1

GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVE #16-01

CENTENNIAL TOWER

Singapore 039190

*Not Authorized
Punery BQ pain*

Ex TBA 7 days

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA 1.6 (2015) SKV4908J

1 pc rear bumper			<i>CM</i> 250.00 c ✓
1 pc LH rear bumper side retainer			<i>M</i> 20.00 c ✓
10 pcs rear bumper clips	@ S\$ 1.80		<i>M</i> 18.00 c ✓
1 pc LH rear bumper reflector			<i>M</i> 36.00 c X
1 pc LH rear bumper mudflap			<i>WT</i> 38.00 c ✓
1 pc LH rear fender			<i>M</i> 630.00 c ✓
1 pc LH rear fender inner shield			<i>M</i> 35.00 c X
10 pcs LH rear fender inner shield clips	@ S\$ 1.80		<i>M</i> 18.00 c X
1 pc LH taillamp			<i>M</i> 190.00 c —
1 pc LH taillamp clips			<i>M</i> 5.00 c —
1 pc bootlid logo			<i>M</i> 30.00 c X
1 pc bootlid "ELANTRA" emblem			<i>M</i> 38.00 c X
1 pc bootlid "GLS" emblem			<i>M</i> 26.00 c X
1 pc fuel lid cover			<i>M</i> 38.00 c X
1 pc LH rear door			<i>M</i> 520.00 c ✓
1 pc LH rear door black sticker-No.1			<i>M</i> 24.00 c —
1 pc LH rear door black sticker-No.2			<i>M</i> 24.00 c —
1 pc LH rear door black sticker-No.3			<i>M</i> 24.00 c ✓
1 pc LH rear door lock			<i>M</i> 130.00 c X
1 pc LH rear door outer handle			<i>M</i> 60.00 c X
1 pc LH frt door			<i>M</i> 630.00 c X
1 pc LH frt door black sticker No.1			<i>M</i> 24.00 c X
1 pc LH frt door black sticker No.2			<i>M</i> 24.00 c X

any key to continue...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000003956-03-000
Our Ref : 023338

Page : 2

No. : 33004

- 1 pc LH frt door outer handle
- 1 pc LH frt door outer handle base
- 1 pc LH frt door weatherstrip
- 1 pc LH wing mirror
- 1 pc LH wing mirror cover
- 1 pc LH wing mirror signal
- 1 pc LH rear wheel bearing

<i>sn</i>	60.00	c	X
<i>sn</i>	150.00	c	X
<i>sn</i>	75.00	c	X
<i>sn</i>	230.00	c	X
<i>sn</i>	100.00	c	X
<i>sn</i>	70.00	c	X
<i>sn</i>	160.00	c	X

3,677.00

Add 10% : 367.70

4,044.70

- 1 pc rear windscreen glass sealant
- 1 pc rear windscreen glass damping seal
- 1 pc LH rear rim
- 1 pc LH rear tyre

<i>sn</i>	40.00	sn	—
<i>sn</i>	20.00	sn	—
<i>sn</i>	580.00	sn	—
<i>sn</i>	380.00	sn	X

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800
1,000.00

To focus taillamps. To check rear wiring and lighting operation.

50.00 *200*

To remove and refit rear windscreen glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works

120.00 *1000*

200.00 *600*

To remove door's fittings

To dismantle and check rear under-carriage. To replace affected portions.

sn 120.00 X

Con't Page 3 ...

金興(興)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming AutoCity
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : MOMVP000003956-03-000
Our Ref : 023338

Page : 3
No. : 33004

To conduct rear wheel alignment test.

To putty and respray on affected portions.

601
100.00
800
1,400.00

Total : S\$ 8,174.70

Singapore Dollars EIGHT THOUSAND ONE HUNDRED SEVENTY FOUR AND CENTS SEVENTY Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be ascertained and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: