



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD 8 TEMASEK BOULEVARD, #04-01 SUNTEC TOWER THREE SINGAPORE 038988			Ref: CS3/EGI23004451/Dqy3m4-1	
			Date: 01/08/2023	
			Code: EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBL 3898U	<b>Veh. Inspected</b>	SJN 7615M
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CDMCG23001041	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	FOO AI NGOH	<b>Assign Date</b>	06/07/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA CAMRY	<b>c.c</b>	2362
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
	<b>Chassis No.</b>	ACV403166068	<b>Colour</b>	BLUE
	<b>Odometer</b>	133022 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/50 ZR18	KUMHO	6 mm
	<b>L/H Front Tyre</b>	225/50 ZR18	KUMHO	6 mm
	<b>R/H Rear Tyre</b>	225/50 ZR18	KUMHO	6 mm
	<b>L/H Rear Tyre</b>	225/50 ZR18	KUMHO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	01/05/2023	<b>Inspection Date</b>	09/05/2023
	<b>Survey held at</b>	ARC MOTORWORKS PTE LTD 10 KAKI BUKIT ROAD 2, #01-21, FIRST EAST CENTRE, SINGAPORE 417868		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	