

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00268622202

Accident Date : 30-Jun-2023

No. : 06869

Date : 04-Jul-2023

Our Ref : 023140 / CHAN

PAGE : 1

CHINA TAIPING INSURANCE (SINGAPORE) P/L

3 ANSON ROAD

#16-00

SPRINGLEAF TOWER

Singapore 079909

Not Authorised

1/1/2023

Mercury Auto Paint

ESTIMATED COST OF REPAIR FOR BMW 840I GRAN COUPE SLE480D

1 pc	Front n/s fender	R 1,850.00	✓
1 pc	Front n/s fender air vent	net 140.00	✓
1 pc	Frt n/s fender inner shield(F)	R 180.00	X
1 pc	Frt n/s fender inner shield(R)	230.00	?
1 pc	Front n/s door	R 2,900.00	✓
1 pc	Front n/s door rubber	R 330.00	✓
1 pc	Front n/s door rubber-outer	R 95.00	?
1 pc	Front n/s door rubber-inner	R 380.00	?
1 pc	Front n/s door handle seal	R 55.00	X
1 pc	Rear n/s door	R 2,900.00	✓
2 pcs	Rear n/s door hinge	@ S\$105.00 R 210.00	X
1 pc	Rear n/s door rubber	R 330.00	✓
1 pc	Rear n/s door rubber -front	R 145.00	✓
1 pc	Rear n/s door rubber -outer	R 420.00	✓
1 pc	Rear n/s door rubber -inner	R 280.00	✓
1 pc	Rear n/s door handle seal	R 55.00	X
1 pc	Front n/s shock absorber	2,200.00	?
1 pc	Front n/s knuckle arm	1,000.00	?
1 pc	Front n/s knuckle bearing hub	580.00	?
1 pc	Front n/s lower arm	480.00	?
1 pc	Front n/s top arm	600.00	?
1 pc	Front n/s ABS sensor	R 260.00	X
1 pc	Rear shock absorber	R 1,850.00	X
1 pc	Rear n/s knuckle arm	780.00	?
1 pc	Rear n/s knuckle bearing hub	700.00	?
1 pc	Rear n/s lower arm	380.00	?
1 pc	Rear n/s top arm	550.00	?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00268622202

Page : 2

1 pc Rear n/s training arm	650.00	✓
1 pc Rear n/s ABS sensor	250.00	✓

	20,780.00	
Add: 10% :	2,078.00	

2 pcs N/s front & rear sport rim	22,858.00	
1 pc Front & rear door rivet (set)	@ \$1500.00	Original rim only ✓ 3,000.00 sn ✓ 60.00 sn ✓
To dismantle and lower front undercarriage	250.00	✓
To dismantle and lower rear undercarriage	250.00	✓
To check and adjust wheel alignment	80.00	✓
To putty and spray replaced parts	1,600.00	1320/
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,200.00	900/
To transfer two left side rim	120.00	40/

Total :	S\$29,418.00	=====

Singapore Dollars Twenty Nine Thousand Four Hundred and Eighteen Only