

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 18 Jul 2023

Preliminary Advice

Vehicle No	: SFP218J	Accident Date	: 30/06/2023
Make	: BMW 318I	Policy No.	: SP2000964955-01
Assignment Date	: 06/07/2023	Excess	: S\$600.00
Date of Inspection	: DESKSTOP SURVEY	Est. Duration of Repair	: 3
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,859.50
Revised Amount	:S\$	5,408.50
Check Items (Estimated)	:S\$	671.00
Total	:S\$	6,079.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	45,576.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,424.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .