



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION

INCIDENT NO.: /20230704/1117

FIRE REPORTED ON: 04 July 2023

TIME OF CALL: 18:27:03 hrs

STATION

COVERAGE: Alexandra Fire Station

LOCATION OF FIRE:

Along Bukit Timah Underpass

Singapore

2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a Mitsubishi lorry (GBJ4281C).

METHOD OF EXTINGUISHMENT: By SCDF crew using a hose line jet and two Compressed Air Foam (CAF) backpacks from fire appliances.

PROBABLE CAUSE OF FIRE: Accidental (Overheating/electrical origin at the engine compartment).

DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the lorry was damaged. Other parts of the lorry sustained heat, smoke and water damage. The road and walls of the underpass sustained varying degrees of heat, smoke and water damage.

3. FATALITY/INJURY INFORMATION

NAME

NRIC/FIN

DEAD/INJURIES SUSTAINED

NIL

NIL

NIL

REPORT ISSUED BY:

NICK LI KEJING

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE

**This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

This is a computer generated report. No signature is required.