

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/23006891/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3R8306Y

at Workshop m/s S10 Hc

of _____

Insured: SNE 494R

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 11k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 0456

Date: _____ Person Contacted: 27A 5413

Vehicle: IN / OUT

Veh No: F3R8306Y Yr Regn: 30/10/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Aerox C.C. 155

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 42/58 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH35646402J073217

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or off road

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/80-14

R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxis

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. mm L/Bal. mm

D.O.A. 26/06/23 D.O.I. 7/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 02/1600

NO 44 85587

19/7/23 4/5 4400 input MR Teo. (Red 5116.90, 54%)

Date/Time, File Pass to?

1) 19/7 19/7 19/7

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: 52 - Claims

Lump Sum / I.B.I. (\$) 4400

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

CHINA-T

Owner : Calvin Ann Wei Jun (91263478)

Nst Abdul
Ali

Accident Date : 26-Jun-23

Vehicle No : FBR8306Y (COE: 29102030)

1/5 # 4400/
4 days
7/7/23

Yamaha Aerox
Vehicle Model : GDR155A CVT
ABS

Estimated Repair Costs

Telephone: 4400-117

Qty	Description List Items		Amount S(\$)
1	Front fork assy	780	\$ 300 980.00
1	Fork under bracket		\$ 300 250.00
1	Front sport rim	335	\$ 300 550.00
1	Front brake disc		\$ 110 220.00
1	Front rim shaft	48	\$ 300 98.00
1	Front rim bearing	50	\$ 300 88.00
1	Front side cover (1 set) - matt	155	\$ 300 260.00
1	Front side inner cover (1set) - matt	160	\$ 300 210.00
1	Front inner compartment		\$ 300 255.00
1	Lower belly cover		\$ 300 195.00
1	Headlamp (LED)	680	\$ 300 980.00
1	Side mirror (1 set) 115	60	\$ 300 180.00
1	Front signals - 1 set		\$ 110 190.00
1	Handle-bar		\$ 300 175.00
1	Handle-bar balancer (1 set) 115	40	\$ 300 125.00
1	Hand grip (1 set)		\$ 110 95.00
1	Brake levers (1 set) 115	75	\$ 300 180.00
2	Footstep panel - L/R/H	300	\$ 300 510.00
2	Footstep lower panel - L/R/H	320	\$ 300 680.00
1	Drove belt cover	148	\$ 300 285.00
1	Air filter cover		\$ 300 165.00
1	Side stand		\$ 300 105.00
1	Main stand		\$ 300 155.00
1	Fairing cover (1 set)	850	\$ 300 1,450.00
Less 10%			\$ 8,381.00
			\$ 838.10
			\$ 7,542.90

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Calvin Ann Wei Jun (91263478)

Accident Date : 26-Jun-23

Vehicle No : FBR8306Y (COE: 29102030)

Yamaha Aerox
Vehicle Model : GDR155A CVT
ABS

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	\$	nr	38.00	10
2	Fork oils	\$	nr	30.00	X
2	Fork oil seals	\$	nr	56.00	X
1	Steering cone (1 set)	\$	nr	120.00	60
1	Rear box	\$	nr	480.00	280
1	Rear box bracket	\$	nr	180.00	X
1	Sticker	\$	nr	120.00	80
				\$	1,024.00

S/No. Labour

1	To provide towing service (LOD) S\$45.00	\$	-	
2	To ckeck wiring and reset headlamp focusing	\$	17 80.00	X
3	To repair body frame	\$	12 420.00	X
4	To provide labour	\$	450.00	300
		\$	950.00	

Grand Total

\$ 9,516.90

Singapore Dollars: Nine Thousand Five Hundred Sixteen and Cents: Ninety only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5301
103
4770.9
430



OFFICIAL RECEIPT

No : 0112 / 23
Date : 3 / 7 / 23

H/P No : 9295 3047

Received From :

Vehicle No. :

From :

Handphone No. :

Amount :

Elia
FBR 83064

low

\$45

Issued By

Note : Vehicle is transported at owner's risk. The company accepts no responsibility for damages or other misdemeanor to your vehicle whilst being transported

045 B