



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23006901/p3

10 MARINA BOULEVARD

Date: 07/07/2023

#48-01 MARINA BAY FINANCIAL CENTRE TOWER

2SINGAPORE 018983

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SH 6182B	Veh. Inspected	SBB 1230L
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04NWE	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	07/07/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/07/2023	Inspection Date
Survey held at	M.S LLH 1, KAKI BUKIT AVENUE 6 #01-67 AUTOBAY@KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--