

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 10 Jul 2023

Preliminary Advice

Vehicle No	: SKM123E	Accident Date	: 03/07/2023
Make	: MERCEDES-BENZ E63	Policy No.	: SP2004744573
Assignment Date	: 07/07/2023	Excess	: S\$1,500.00
Date of Inspection	: 10/07/2023	Est. Duration of Repair	: 4
Inspection At	: MBM WHEELPOWER PTE LTD (SIN MING) 176 SIN MING DRIVE #01-15, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,479.50
Revised Amount	:S\$	3,840.50
Check Items (Estimated)	:S\$	2,599.00
Total	:S\$	6,439.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	360,000.00
COE / PARF Rebate	:S\$	170,846.00
Salvage Value	:S\$	
Margin for Repair	:S\$	189,154.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :According to the repairer, they are not authorise workshop, so they put up the list prices instead of cost plus.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.