

REPAIR ESTIMATE

DATE: 06.07.2023

SLZ2733B

MODEL: Hyundai i40

INSURANCE: ALLIANZ

MVA: LIM T S

VEHICLE NO.: SHA7915P

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper / LRA	1		\$ 553.00
	Rear Bumper Under Cover / DEF	1		\$ 228.00
	Rear Bumper Clips / NEL	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector RH ?	1		\$ 32.00
	SUB TOTAL			\$ 835.00
	LESS 25%			\$ 208.75
	DISCOUNTED TOTAL			\$ 626.25
	Rear Bumper Mat / NEL	1		\$ 50.00
	Reverse Sensors / XJVC	1		\$ 135.70
	Rear Fender Adv. Sticker RH / LH / NEL	2	\$ 100.00	\$ 200.00
	NETT TOTAL			\$ 385.70
	SPARE PARTS TOTAL			\$ 1,011.95
	<u>Labour Charge</u>			
	Panel Beating		280	\$ 300.00
	Spray Painting Charge		250	\$ 300.00
	R/I Reverse Sensors		30	\$ 120.00
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 1,731.95

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKIC
2/7/2023 1615
LIS
2 DPM

CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

- LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before / after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date: