

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23003360/TCY3M4-1**Date:** 13/07/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle No : SMG2554P **Insured Vehicle No :** SLN1937A

Date of Loss: 23/03/2023 Nature of Claim: TP Claim No: MFL2023D0003258

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMG2554P**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A)

Engine No: 2ZR0C35168

Reg. Date: 12/12/2018 (Man. Year: 2018)

Chassis No: ZWR800344687

Colour: Grey

Odometer: 343102 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,476.02	1,796.02	1,680.00	48.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	990.00	960.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,426.02	2,786.02	2,640.00	48.65
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	5,426.02	2,200.00	3,226.02	59.45

INSPECTION

Date of Assignment: 07/07/2023

Date Inspected: 20/04/2023 Inspected At:

Trident Auto Service Centre Pte Ltd (HQ)
8 Kaki bukit Ave 4, #02-42 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2554P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S FENDER	Repair	200.54 FL	*- FL
2	1		*N/S ROCKER PANEL SIDE SKIRT	Repair	700.12 FL	*- FL
3	1		*N/S SLIDING DOOR	Damaged	1,800.17 FL	*1,594.70 FL
4	1		*N/S SLIDING DOOR RUBBER	Not Necessary	200.53 FL	*- FL
5	1		*REAR N/S TYRE (DEPRECIATION)	Not Necessary	400.00 FS	*- FS
6	1		*REAR N/S WHEEL RIM	Damaged	900.00 FS	*600.00 FS
					Sub Total (\$\$)	4,201.36 2,194.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	725.34 398.68
					Total Parts (\$\$)	3,476.02 1,796.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	300.00	60.00
2	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
3	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD ; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	400.00
4	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	750.00	500.00
Gross Labour Cost (\$\$)			1,950.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >