



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/III23003360/Twy3-1	
INDIA INTERNATIONAL INSURANCE PL				Ref: CS3/III23003360/y3	
64 CECIL STREET				Date: 31/03/2023 07/07/2023	
#05-02 IOB BUILDING SINGAPORE 049711				Code: III2	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SLN 1937A		Veh. Inspected SMG 2554P	
Policy No.				Coverage (\$) 0.00	
Claim No.				Excess (\$) 0.00	
Assign From		JACELYN LOH		Assign Date 30/03/2023 07/07/2023	
2. Vehicle Particulars & Condition					
Make & Model		c.c		0	
Engine No.		HIDDEN		Year of Reg.	
Chassis No.				Colour	
Odometer		-		Steering	
Brakes				Modification	
General					
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
5. General Information					
Accident Date		23/03/2023		Inspection Date	
Survey held at		TRIDENT AUTO SERVICE CENTRE PTE LTD			
		8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					