



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS3/CTI22011296/Dvp3e2-1 Date: 12/07/2023 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | CB 5646H | Veh. Inspected | SLM 7378D | |
| Policy No. | DMB1SNW00015622101 | Coverage (\$) | 0.00 | |
| Claim No. | SNM22D208041/C02/LEWLC | Excess (\$) | 0.00 | |
| Assign From | JENNY LEW | Assign Date | 05/07/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | B.M.W. 130I 3.0 | c.c | 2996 | |
| Engine No. | HIDDEN | Year of Reg. | 2008 | |
| Chassis No. | WBAUB12090VE72036 | Colour | GREY | |
| Odometer | 177357 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/40 R18 | PIRELLI | 6 mm | |
| L/H Front Tyre | 225/40 R18 | PIRELLI | 6 mm | |
| R/H Rear Tyre | 225/40 R18 | PIRELLI | 6 mm | |
| L/H Rear Tyre | 225/40 R18 | PIRELLI | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 08/11/2022 | Inspection Date | 10/11/2022 | |
| Survey held at | LUCK7WIN PTE LTD 51 UBI AVENUE 1 #01-11 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |