PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/TP/0634/2023/EQ

DATE : 7-Jul-23 **WIP** : 27538

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

YOUR INSURED VEH NO: SLE 7175 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR GOSS BENJAMIN PAUL

ADDRESS : 25 SUNSET SQUARE

SINGAPORE 597322

TELEPHONE:HP +65 83238712TYPE OF CLAIM:THIRD PARTY CLAIMPOLICY NO:2070177615-01

VEHICLE NO : SMX 2057 T

MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC

 MODEL YEAR
 : 30/12/2020

 ENGINE NO
 : CZD C13892

CHASSIS NO : WAUZZZF31M1034769

MILEAGE : DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 3-Jul-23

PLACE OF ACCIDENT : COLD STORAGE SERVICE ROAD OFF SUNSET WAY IN CLEMENTI

(CLEMENTI ARCADE) ONE WAY SERVICE ROAD AND

STATIONARY CAR OPENED DOOR AS OUR CAR MOVED DOWN

MINOR ROAD AT CLEMENTI ARCADE).





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 2057 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI- LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECCESARY.	S/N	\$ 400.00	
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,200.00	
3	TO RESPRAY RHS FRONT DOOR AND DOOR HANDLE.		\$ 1,500.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 3,292.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 2057 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 3,192.00	
2	FRONT DOOR OUTER SEAL - RH	1	\$ 196.00	
3	FRONT DOOR ATTACHMENT PARTS	1	\$ 173.00	
4	FRONT DOOR CATCH	1	\$ 141.00	
5	FRONT EXTERIOR DOOR HANDLE	1	\$ 754.00	
6	FRONT DOOR HANDLE COVER CAP - RH	1	\$ 32.00	
7	FRONT DOOR HANDLE MOUNTING BAR - RH	1	\$ 180.00	
8	FRONT DOOR HANDLE BOWDEN CABLE - RH	1	\$ 64.00	
9	FRONT DOOR COVER - RH	1	\$ 299.00	
10	FRONT TYRE PRESSURE DATA PLATE	1	\$ 36.00	
11	SUNDRIES		\$ 500.00	
	TOTAL SPARE PARTS	:	\$ 5,567.00	
	TOTAL LABOUR CHARGES	:	\$ 3,292.00	
	GRAND TOTAL	:	\$ 8,859.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO ALLAN WU

BODY REPAIR MANAGER CLAIMS CONSULTANT