

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CY/23006940/U923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD7875H

at Workshop m/s: Mub City 32/kelebuluf

Insured: SJ2481P

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$58k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 338e

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 932083

Veh No: SLD7875H Yr Regn: 28/06/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / Diesel

Make: Ssangyong stavic c.c 2157

Colour: meroon A/C: Insured / Std / NI / NA

Sp.Reading: 15770f T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPTVOBIESGP111454

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R16 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Raxus

Front: 6 mm Rear: 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/7/23 D.O.I. 11/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

18/7/23 4586400 Informed Mr Lee Ured \$5565.70, 47%

Date/Time, File Pass to?

1) 18/7/23

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

____ S + RS ____ SI

Photos

Others

TOTAL

Report Format: EZ Claims

Lump Sum / I.B.L. (\$) 6400

Auto City Pte Ltd

32 Kaki Bukit Crescent, Singapore 416262

Tel: 6846 8855 (Raymond)

Not Allowed
4/5 @ 6400
4 days.
Wholesale Afterpay
11/7/23

Vehicle number: SLD7875H

Vehicle Made & Model: SSANGYONG STANIC

Qty	Nett Items	Amount \$
1	Tailgate <i>body 20</i>	2,160.00
1	Tailgate glass moulding <i>new</i>	182.00
1	Tailgate logo <i>new</i>	112.00
2	Tailgate lamps - L/R @ 482 <i>new</i>	964.00
1	Tailgate inner lock <i>new/3m</i>	315.00
1	Tailgate inner trim board <i>2x10cm</i>	560.00
1	Tailgate w/strip <i>new</i>	215.00
2	Taillamps - L/R @ 610 <i>new</i>	1,210.00
1	Rear bumper <i>DD/de</i>	1,360.00
2	Rear bumper reflectors - L/R @ 115 <i>MS one 2/5/17</i>	230.00
1	Rear bumper reinforcement <i>3m</i>	1,260.00
2	Rear bumper side retainers - L/R @ 110 <i>new</i>	220.00
1	Rear end panel <i>DD/3m</i>	865.00
1	Rear end panel garnish <i>new</i>	220.00
Sub-total		9,873.00
Less 10%		987.30
Total List		8,885.70

6954
112
62886
80886
6230

Special Nett Items		
1 set	Tailgate glass sealant <i>new</i>	80.00
1 set	Rear bumper clip <i>new</i>	60.00
1	Rear reverse camera <i>new</i>	480.00
Total Special Nett		620.00

Labour charges		
To check rear electrical wiring		50.00
To remove, refix tailgate glass		180.00
Transfer & reinstall tailgate components to new tailgate		150.00
To respray undercoating		100.00
To respray painting and etc		1,080.00
Panel beating, cut, weld remove & replacing above parts		900.00
Total Labour		2,460.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 11,965.70

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date: