


Section A - Accident Details

Registration Number	SHD6397A
Case Reference Number	TAX/07/23/2020
Registration Date	26/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	ABDUL JALEEL BIN KADER MYDIN
Type of Accident	Side Swipe
Accident Date and Time	7/7/23 6:45 PM
Accident Reported Date and Time	8/7/23 11:16 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118828
Special Instruction to ARC, if any	TP/ TOWED
Prepared Date and Time	8/7/23 12:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$8,582.22	\$0.00
Total Other Cost	\$1,422.88	\$0.00
TOTAL COST	\$12,813.10	\$0.00
Lump Sum Total	\$12,800.00	\$0.00
Number of Repair Days	8.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	08/07/2023 12:17 PM	
Signature		x <i>Done - 4p 90010068 5 days L/S 10/07/23 @ 1420 Resg after repair</i>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Date: _____
User ID: _____

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	500
Total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	200
TO RESPRAY FRONT FENDER LH	\$378.00	200
TO RESPRAY VIEW MIRROR	\$220.00	70
TO RESPRAY FRONT DOOR LH	\$378.00	X
RESPRAY WHEEL CAP	\$220.00	X
TO RESPRAY RIM	\$220.00	X
Total Spray Painting & Panel Beating	\$1,794.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE <i>immo</i>	\$56.00	7
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	60
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	60
TO REMOVE AND REFIT TYRE	\$120.00	X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88	✓
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	150
TO WASH AND VACUUM	\$60.00	X
TO REPLACE SUNDRY PARTS	\$100.00	X
Total Other Costs	\$1,422.88	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	✓
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	✓
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	✓
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	✓
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	✓
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	25.00	\$795.53	Replace	✓
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	✓
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	✓
		53857-12010	RETAINER, FR WHEEL RH	1.00	\$3.50	25.00	\$2.63	Replace	X
		53828-47070	PROTECTOR, FR FENDER LH	1.00	\$101.80	25.00	\$76.35	Replace	X
		53852-47041	PAD, FR WHEEL LH	1.00	\$65.00	25.00	\$48.75	Replace	X
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	X
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	✓
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	X
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	?

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		43212-47040	KNUCKLE, STEERING, LH	1.00	\$717.50	25.00	\$538.13	Replace	?
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$823.20	25.00	\$617.40	Replace	?
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	1.00	\$511.40	25.00	\$383.55	Replace	?
		87940-47440	MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,454.40	10.00	\$1,308.96	Replace	X Repair
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	X
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	X
Total					\$13,336.84		\$10,727.77		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: --

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6397A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F42154
Chassis No.:	JTDKB3FU103089381
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	26 Dec 2019
First Registration Date:	26 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$10,897.00
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$14,243.00
Total Rebate Amount:	\$25,140.00
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Jul 2023

OK