

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23006945/TNY3E2**Date:** 18/07/2023REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MZC00196

Claimant Vehicle No : SHC3181E**Insured Vehicle No :** SND7947K

Date of Loss: 07/07/2023

Nature of Claim: TP Claim No: M2303921

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC3181E**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)

Engine No: 2ZR2B86589

Reg. Date: 09/01/2019 (Man. Year: 2018)

Chassis No: JTDKB3FUX03078010

Colour: Blue

Odometer: 368663 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,149.00	1,149.00	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	300.00	300.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,460.00	1,460.00	0.00	0.00
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,460.00	1,150.00	310.00	21.23
+ GST 8.00/8.00% (S\$)	116.80	92.00	24.80	21.23
Nett Amount (S\$)	1,576.80	1,242.00	334.80	21.23

INSPECTION

Date of Assignment: 10/07/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/07/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 1.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3181E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT SIDE MIRROR ASSY RH	Cracked	1,390.10 FL	*1,390.10 FL
2	1		*FRT SIDE MIRROR COVER RH	Distorted	141.90 FL	*141.90 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					1,532.00	1,532.00
- List Item Discount on L Items 25.00/25.00% (\$)					383.00	383.00
Total Parts (\$)					1,149.00	1,149.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	120.00	120.00
2	SPRAYPAINT	New	120.00	120.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	TOWING CHARGE	New	60.00	60.00
Gross Labour Cost (S\$)			300.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >